

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014381/DVD3Q2
Date: 05/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNA00008782001
Claimant Vehicle No :	SCE6900B	Insured Vehicle No :	PC7051B
Date of Loss:	21/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D204972/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCE6900B	Engine No:	4A910126014
Make & Model:	MITSUBISHI LANCER, 1.5 (A)	Chassis No:	JMYSRCY2AAU000382
Reg. Date:	26/02/2010 (Man. Year: 2009)	Odometer:	220836 km
Colour:	Red		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,926.50	3,229.33	12,697.17	79.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	1,030.00	2,770.00	72.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,726.50	4,259.33	15,467.17	78.41
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	19,726.50	3,400.00	16,326.50	82.76
+ GST 7.00/7.00% (S\$)	1,380.86	238.00	1,142.86	82.76
Nett Amount (S\$)	21,107.36	3,638.00	17,469.36	82.76

INSPECTION

Date of Assignment:	01/03/2021	
Date Inspected:	23/12/2020 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	4.0 days	

3/5/2021

Adjuster Report

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2021)
Parts:	143	MITSUBISHI LANCER 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCE6900B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,190.00 FL	*- FL
2	2		*BONNET HINGE LH/RH	Not Necessary	140.00 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	182.00 FL	*- FL
4	1		*BONNET LOCK	Bent	160.00 FL	*160.00 FL
5	1		*BONNET STRIKER LOCK	Not Necessary	88.00 FL	*- FL
6	1		*BONNET SEAL	Not Necessary	58.00 FL	*- FL
7	2		*HEAD LAMP LH/RH	Mounting Cracked	2,196.00 FL	*1,232.00 FL
8	2		*HEAD LAMP LOWER BRACKET LH/RH	Not Necessary	160.00 FL	*- FL
9	2		*HEAD LAMP PANEL LH/RH	Not Necessary	356.00 FL	*- FL
10	1		*FRONT BUMPER	Distorted/Bent	1,158.00 FL	*882.70 FL
11	2		*FRONT BUMPER SIDE RETAINER LH/RH	Serviceable	140.00 FL	*- FL
12	1		*FRONT BUMPER GRILLE	Broken	387.00 FL	*256.00 FL
13	1		*FRONT BUMPER GRILLE CHROME	Broken	457.00 FL	*177.00 FL
14	1		*FRONT BUMPER GRILLE LOGO	Broken	97.00 FL	*97.00 FL
15	1		*FRONT BUMPER LOWER GRILLE	Mounting Broken	214.00 FL	*99.00 FL
16	2		*FRONT BUMPER FOG LAMP GARNISH LH/RH	Not Necessary	280.00 FL	*- FL
17	1		*FRONT BUMPER UNDER COVER	Not Necessary	325.00 FL	*- FL
18	1		*FRONT REINFORCEMENT BAR	Dented/Bent	826.00 FL	*326.00 FL
19	1		*FRONT SUPPORT PANEL	Not Necessary	967.00 FL	*- FL
20	1		*HORN	Not Necessary	65.00 FL	*- FL
21	1		*A/C CONDENSOR ASSY	Not Necessary	1,221.00 FL	*- FL
22	1		*A/C CONDENSOR LOW PRESSURE PIPE	Not Necessary	356.00 FL	*- FL
23	1		*A/C CONDENSOR HIGH PRESSURE PIPE	Not Necessary	312.00 FL	*- FL
24	1		*A/C CONDENSOR DISCHARGE PIPE	Not Necessary	392.00 FL	*- FL
25	1		*RADIATOR ASSY	Not Necessary	1,461.00 FL	*- FL
26	1		*RADIATOR TOP HOSE	Not Necessary	49.00 FL	*- FL
27	1		*RADIATOR BOTTOM HOSE	Not Necessary	64.00 FL	*- FL
28	1		*RADIATOR FAN MOTOR	Not Necessary	422.00 FL	*- FL
29	1		*RADIATOR FAN BLADE	Not Necessary	268.00 FL	*- FL
30	1		*RADIATOR FAN COWLING	Not Necessary	443.00 FL	*- FL
31	1		*FRONT SUPPORT PANEL TOP GARNISH	Mounting Cracked	312.00 FL	*175.00 FL
32	1		*FRONT BUMPER BRACKET	Bent	323.00 FL	*89.00 FL
33	2		*FRONT FENDER LH/RH	Not Necessary	1,746.00 FL	*- FL
34	2		*FRONT FENDER INNER SHIELD LH/RH	Not Necessary	270.00 FL	*- FL
35	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
38	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
39	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
42	1		*COOLANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT NO PLATE & CASING	Broken/Bent	100.00 FS	*45.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					17,635.00	3,578.70
- List Item Discount on L Items 10.00/10.00% (S\$)					1,708.50	349.37
Total Parts (S\$)					15,926.50	3,229.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,400.00	500.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,400.00	500.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
4	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	100.00	0.00
5	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	100.00	0.00
6	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
7	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			3,800.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >