

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20014384/T1PA3Q2
Date: 11/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070091949
Claimant Vehicle No :	SHB3065M	Insured Vehicle No :	GBG1287Y
Date of Loss:	22/12/2020	Nature of Claim:	TP
		Claim No:	0818953320SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB3065M	Engine No:	G4LEKU298131
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU164754
Reg. Date:	10/07/2019 (Man. Year: 2019)	Odometer:	222098 km
Colour:	Yellow		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	854.64	509.92	344.72	40.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	720.00	230.00	24.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,804.64	1,229.92	574.72	31.85
+ GST 7.00/7.00% (S\$)	126.32	86.09	40.23	31.85

Nett Amount (\$)		1,930.96	1,316.01	614.95	31.85
Global Sum Settlement (\$)			0.00		

INSPECTION

Date of Assignment:	23/12/2020			
Date Inspected:	23/12/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969	
Estimated Period of Repair:	2.0 days			

Adjuster:	MOHD TAUFIKH BIN HAMID	Manager:	CHEW HSIAO TONG
------------------	------------------------	-----------------	-----------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	500.00	320.00
2	SPRAYPAINT ON AFFECTED AREA	New	450.00	400.00
Gross Labour Cost (S\$)			950.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >