

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20014389/R1BA3Q2  
**Date:** 07/04/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SMT3768P	<b>Insured Vehicle No :</b>	SH8964Z
Date of Loss:	17/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120332

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMT3768P</b>	Engine No:	G4FGKH755793
Make & Model:	KIA CERATO, 1.6 LX (A)	Chassis No:	KNAF1416ML5069571
Reg. Date:	03/06/2020 (Man. Year: 2019)	Odometer:	12348 km
Colour:	Multi-colour		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,571.64	2,290.67	1,280.97	35.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,635.00	1,195.00	440.00	26.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,206.64</b>	<b>3,485.67</b>	<b>1,720.97</b>	<b>33.05</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>364.46</b>	<b>244.00</b>	<b>120.46</b>	<b>33.05</b>
<b>Nett Amount (S\$)</b>	<b>5,571.10</b>	<b>3,729.67</b>	<b>1,841.43</b>	<b>33.05</b>
<b>+ Loss of Use (7.0 x S\$80.00/day) (S\$)</b>		560.00		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>4,318.67</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,150.00</b>		

### INSPECTION

Date of Assignment:	23/12/2020		
Date Inspected:	23/12/2020	Inspected At:	Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	5.0 days		

4/7/2021

Adjuster Report

**Adjuster:** MOHD RASUL

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS**

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2021)
<b>Parts:</b> 143	KIA CERATO 1.6 LX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMT3768P)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID (NPA)	Not Necessary	0.00 FL	*- FL
2	1		*REAR LAMP OUTER RH	Serviceable	355.40 FL	*- FL
3	1		*REAR BUMPER	Cracked	575.20 FL	*575.20 FL
4	10		*REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
5	1		*REAR BUMPER SIDE RETAINER RH	Necessary	45.50 FL	*45.50 FL
6	1		*REAR BUMPER INNER BRACKET RH	Serviceable	54.30 FL	*- FL
7	1		*REAR BUMPER SIGNAL LAMP RH	Cracked	285.60 FL	*285.60 FL
8	1		*REAR BUMPER SIGNAL LAMP COVER RH	Cracked	55.10 FL	*55.10 FL
9	1		*REAR BUMPER LOWER GARNISH	Cracked	284.70 FL	*284.70 FL
10	1		*REAR BUMPER REINFORCEMENT	Cracked	355.20 FL	*355.20 FL
11	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Serviceable	82.60 FL	*- FL
12	1		*REAR BUMPER REINFORCEMENT ARM RH	Serviceable	75.80 FL	*- FL
13	1		*REAR END PANEL	Repair	455.20 FL	*- FL
14	1		*REVERSE SENSOR	Serviceable	220.00 FS	*- FS
15	1		*END PANEL SEALANT	Not Necessary	40.00 FS	*- FS
16	1		*REAR BUMPER ADV STICKER	Necessary	500.00 FS	*450.00 FS
17	1		*REAR BOOTLID ADV STICKER	Necessary	400.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>3,839.60</b>	<b>2,456.30</b>
- List Item Discount on L Items 10.00/10.00% (S\$)	267.96	165.63
<b>Total Parts (S\$)</b>	<b>3,571.64</b>	<b>2,290.67</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO CARRY OUT REAR REPAIR	New	800.00	500.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	35.00	35.00
3	TO SPRAY PAINTING ON REAR AFFECTED AREA	New	700.00	600.00
4	SPRAY RUST PROOFING ON AFFECTED AREA	New	40.00	0.00
5	TO DETACH & RENEW REVERSE SENSOR	New	60.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,635.00</b>	<b>1,195.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >