3/22/2021 Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20014395/R1TD3Q2

Date: 22/03/2021

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29147094AT2

**Claimant Vehicle** SKU2741R **Insured Vehicle No:** SLG8907C

No:

22/12/2020 Nature of Claim: ΤP Claim No: 632334 Date of Loss:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Rea No: **SKU2741R** 

Make & Model: CITROEN C4 PICASSO, 1.6 I EHDI ETG6 (A) Engine No: 10JBEX3057374 Reg. Date: 15/07/2015 (Man. Year: 2015) Chassis No: VF73D9HC8FJ659158

Colour: Odometer: 91141 km Blue

**Engine Capacity:** 1560 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes **Engine Modification:** Pre-accident Condition: Nο

**CONDITION OF TYRES** 

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side:

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,877.10	4,374.40	1,502.70	25.57
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,260.00	1,150.00	1,110.00	49.12
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,137.10	5,524.40	2,612.70	32.11
	Approved Total (Overridden) (S\$)		4,350.00		
	Nett Amount (S\$)	8,137.10	4,350.00	3,787.10	46.54

**INSPECTION** 

Date of Assignment: 23/12/2020

Xinya Auto Services Pte Ltd (HQ) Date Inspected: 29/12/2020 Inspected At: Blk 1002, #01-75, Bukit Merah Lane 3

Singapore 159719

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

## REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Mar 2021)

Parts: 144 CITROEN C4 PICASSO 1.6 I EHDI ETG6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKU2741R) Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	822.00 FL	*- FL
2	2		*REAR BUMPER REFLECTOR	Serviceable	406.00 FL	*- FL
3	1		*REAR ENFORCEMENT	Serviceable	425.00 FL	*- FL
4	1		*TAIL GATE	Cracked	2,185.00 FL	*2,185.00 FL
5	1		*TAIL GATE LOWER GARNISH	Cracked	520.00 FL	*520.00 FL
6	2		*TAIL LAMP	Cracked	680.00 FL	*680.00 FL
7	1		*CITREON LOGO	Necessary	108.00 FL	*108.00 FL
8	1		*CITREON EMBLEM	Necessary	108.00 FL	*108.00 FL
9	1		*C4 EMBLEM	Necessary	82.00 FL	*82.00 FL
10	1		*E HDI EMBLEM	Necessary	86.00 FL	*86.00 FL
11	1		*PICASSO EMBLEM	Necessary	112.00 FL	*112.00 FL
12	10		*BUMPER CLIPS	Necessary	100.00 FL	*100.00 FL
13	1		*NOS PLATE W/CASING	Scratched	50.00 FS	*35.00 FS
14	1		*TAIL GATE INNER BOARD GARNISH	Broken	785.00 FL	*785.00 FL
15	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.	-		
				Sub Total (S\$)	6,519.00	4,851.00
			- List Item Discount on	L Items 10.00/10.00% (S\$)	641.90	476.60
				Total Parts (S\$)	5,877.10	4,374.40
					5,8//.10	_

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE & REPLACE REAR BUMPER, TAILGATE, TAILLAMPS AND PANEL BEAT & ALIGN	New	1,000.00	400.00
2	TO PUTTY & SPRAY PAINT REAR BUMPER, TAIL GATE (OUTER & INNER) AND OTHER AFFECTED AREA	New	800.00	600.00
3	TO CHECK & RECTIFY WIRING	New	80.00	30.00
4	TUFF KOTE	New	220.00	0.00
5	TO REMOVE & REFIT WINDSCREEN AND CHECK FOR WATER LIGHT	New	160.00	120.00
	Gross Labou	2,260.00	1,150.00	
	Report was unsubmitted during this p	rint-out		

< END OF ESTIMATES >