

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20014399/QTD3E2

Date: 14/04/2021

REFERENCE

Insured/Claimant: ALLIMRAN BIN LOMRI Policy No: DMHCSNW00008152000

Date of Loss: 20/12/2020

Nature of Claim: OD

Claim No: SNM20D204984/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC1593A**

Make & Model: PEUGEOT 5008, 1.6 D e-Hdi ETG (A)

Engine No: 10JBFT0099744

Reg. Date: 21/01/2016 (Man. Year: 2015)

Chassis No: VF30E9HD8FS212614

Colour: Brown

Odometer: 103491 km

Engine Capacity: 1560 cc

Market Value/New Car Price: S\$50,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,975.00	4,400.00	1,575.00	26.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	399.00	348.60	50.40	12.63
Paintwork Labour	405.16	405.16	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,779.16	5,153.76	1,625.40	23.98
- Excess (S\$)	1,250.00	1,250.00	0.00	0.00
(S\$)	5,529.16	3,903.76	1,625.40	29.40
+ GST 7.00/7.00% (S\$)	387.04	273.26	113.78	29.40
Nett Amount (S\$)	5,916.20	4,177.02	1,739.18	29.40

INSPECTION

Date of Assignment: 23/12/2020 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

Date Inspected: 24/12/2020 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)

Estimated Period of Repair: 6.0 days
6 Marsiling Lane
Singapore 739145

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2021)
Parts:	M1-SUV	PEUGEOT 5008 1.6 D e-Hdi ETG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGC1593A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		5,975.00 F	*4,305.00 F
2	1		*FUSE BOX BRACKET	Broken	-	*95.00 F
F=Franchise part.						
Total Parts (S\$)					5,975.00	4,400.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINT	New	405.16	405.16
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	399.00	348.60
Gross Labour Cost (\$)			804.16	753.76

Report was unsubmitted during this print-out.

< END OF ESTIMATES >