



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2100535

INV Date 25/01/2021

Reference CC3/EQI20014405/Kvd3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 499D

Insured Veh. GBG 6914M

Claim No. DM20HO01813/JT

Policy No.

Accident Date 03/12/2020

Inspection Date 04/12/2020

Description	Total
Survey Inspection	300.00
Digital Photographs	
Transportation	
Subtotal	300.00
GST (7%)	21.00
Grand Total	321.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CC3/EQI20014405/Kvd3e2 Date: 25/01/2021 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 6914M	Veh. Inspected	SHD 499D	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM20HO01813/JT	Excess (\$)	0.00	
Assign From		Assign Date	04/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1ABL15AUC283457	Colour	METALLIC WHITE / RED	
Odometer	536963 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SAILUN	8 mm	
L/H Front Tyre	215/60 R16	SAILUN	8 mm	
R/H Rear Tyre	215/60 R16	SAILUN	8 mm	
L/H Rear Tyre	215/60 R16	SAILUN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2020	Inspection Date	04/12/2020	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 499D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BENT	561.70	561.70
1	BUMPER LOWER REAR	DENTED / CUT	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE RH REAR	CRACKED	82.10	82.10
1	BUMPER RETAINER RH REAR	DISTORTED	59.80	59.80
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER BEAM REAR	BENT	547.80	547.80
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER REFLECTOR LH	SERVICEABLE	16.60	-
1	BUMPER REFLECTOR RH	SCRATCHED	16.60	16.60
1	OUTER PANEL REAR (END PANEL)	BENT	745.80	745.80
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	404.56	404.56
1	BOOT REAR	TO REPAIR SEE LABOUR	1,677.20	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	277.70	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	277.70	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	246.60	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	41.70	-
1	BOOT FINISHER	SERVICEABLE	344.70	-
1	BOOT BADGE 'RENAULT'	NOT NECESSARY	82.40	-
1	BOOT BADGE	NOT NECESSARY	95.80	-
1	BBOOT FINISHER	SERVICEABLE	344.70	-
1	TAILLAMP RH	BROKEN	401.40	401.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	FENDER PANEL REAR RH	BENT	1,933.20	1,933.20
1	WHEELARCH REAR RH	SERVICEABLE	275.40	-
1	SPARE TYRE BOARD	SERVICEABLE	680.90	-
1	SPARE WHEEL PANEL	TO REPAIR SEE LABOUR	1,229.40	-
1	SPARE WHEEL PANEL BRACKET LH L70Y	TO REPAIR SEE LABOUR	70.60	-
1	SPARE WHEEL PANEL BRACKET RH L70Y	TO REPAIR SEE LABOUR	69.20	-
	LESS 10% DISCOUNT		-1,226.74	-516.49
			11,040.62	4,648.37
1	BOOT WEATHERSTRIP (50%) (SN)	DISTORTED / CUT	178.20	89.10
	LESS 10% DISCOUNT		-17.82	-
			160.38	89.10
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	DENTED / CUT	700.00	400.00
1	BOOT FINISHER NUT L70Y (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	SET WHEELARCH CLIP (SN)	NECESSARY	60.00	60.00
1	SET FENDER CLIP (SN)	NOT NECESSARY	35.00	-
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	REAR NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	120.00	-
1	REAR BOOT STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	80.00	-
2	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00

Report Ref No. CC3/EQI20014405/Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	200.00	-
1	WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	130.00	30.00
1	REAR BOOT STICKER '6555-3333' (SN)	NOT NECESSARY	80.00	-
			1,879.82	662.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	660.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, SPARE WHEEL PANEL, SPARE WHEEL PANEL BRACKET LH L70Y AND SPARE WHEEL PANEL BRACKET RH L70Y.		3,000.00	1,200.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		300.00	120.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
			7,370.00	2,220.00
GRAND TOTAL			20,450.82	7,619.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,100.00

Report Ref No. CC3/EQ120014405/Kvd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 03/12/2020 23:47 (SGT)
Date of Accident 03/12/2020 13:20 (SGT)
Exact Location of Accident 158 Lor 1 Toa Payoh, Toa Payoh Int, Block 158, Singapore 310158
Additional Location Information ALONG LOR 1 TOA PAYOH AFTER JUNCTION LOR 2
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD499D

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
Company Reg No 2XXXXX878K
Email Address Claims@transcab.com.sg
Mobile Phone No (Phone) +65-62866666
Alternative Phone No (Office) +65-62866666

VEHICLE PARTICULARS

Manufacturer Renault
Model Latitude
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi

INSURANCE COMPANY

Name of Insurance Company Axa
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number VFX/P2348706
Cover Note Number NA

DRIVER

Name of Driver LIANG CHWEE CHOON
NRIC No SXXXX697H
Date Of Birth 17/02/1952
Occupation Outdoor

Date Of Driving Pass	06/02/1976
Driving experience	44 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97322920
Alt. Phone Number	-
Email Address	Claims@transcab.com.sg
Address	NA
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING ALONG LOR 6 TOA PAYOH TOWARDS LOR 1 TOA PAYOH . AFTER CROSS JUNCTION OF LOR 2 TOA PAYOH , I OPENED MY DOUBLE SIGNAL AND STATIONARY AT SIDE OF THE ROAD TO CHECK MY GPS . SUDDENLY VEHICLE B COLLIDED ONTO REAR OF MY VEHICLE . NO INJURIES INVOLVED .

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG6914M
Vehicle Manufacturer	Nissan
Vehicle Model	Nv200
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	CHANG BOON CHYE
NRIC No	SXXXX654B
Contact Number	(Phone) +65-90292989
Address	-

REPORT TO ATTORNEY GENERAL

REFER TO ATTACHED STATEMENT

• The degree to which particular jet streams may change

Reporting Contact: **Transportation Engineering**
 Bureau

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG LOR 6 TOA PAYOH TOWARDS LOR 1 TOA PAYOH . AFTER CROSS JUNCTION OF LOR 2 TOA PAYOH , I OPENED MY DOUBLE SIGNAL AND STATIONARY AT SIDE OF THE ROAD TO CHECK MY GPS . SUDDENLY VEHICLE B COLLIDED ONTO REAR OF MY VEHICLE . NO INJURIES INVOLVED .

Taxi Voucher No.:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 499D

INSPECTION

