12/14/21, 10:47 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014406/KPA3Q2

Date: 14/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800003697

Claimant Vehicle SMH9315L Insured Vehicle No: SLV272Z

Date of Loss: 22/12/2020 Nature of Claim: TP Claim No: 6089157661SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMH9315L

Make & Model: TOYOTA ALPHARD, 2.5 CVT ELEGANCE S/R (A) Engine No: 2ARH519009

Reg. Date: 06/08/2015 (Man. Year: 2015) Chassis No: JTNGF3DH508000183

Colour: Metallic Black Odometer: 157675 km

Engine Capacity: 2494 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18 Rear Tyre Size: 235/50R18
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,394.80	3,304.22	1,090.58	24.82
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,280.00	1,710.00	570.00	25.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	6,674.80	5,014.22	1,660.58	24.88
	+ GST 7.00/7.00% (S\$)	467.24	351.00	116.24	24.88
	Nett Amount (S\$)	7,142.04	5,365.22	1,776.82	24.88
	+ Car Rental (5.0 x S	\$130.00/day) (S\$)	650.00		
	+ Do	c/Search Fee (S\$)	8.00		
		Nett Liability (S\$)	6,023.22		

INSPECTION

Date of Assignment: 23/12/2020

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 23/12/2020 Inspected At: Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 5.0 days

Adjuster: HOW MEI KWAN Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Bent	601.90 FL	*601.90 FL	
2	2		*REAR BUMPER REFLECTOR	Serviceable	113.80 FL	*- FL	
3	6		*REAR BUMPER CLIP	Necessary	21.00 FL	*21.00 FL	
4	2		*REVERSE SENSOR	Distorted / Shorted	763.20 FL	*763.20 FL	
5	1		*REAR TAILGATE	Bent	2,019.70 FL	*2,019.70 FL	
6	1		*TAILGATE EMBLEM -ALPHARD	Necessary	68.20 FL	*68.20 FL	
7	1		*TAILGATE INNER LOCK	Jammed / Dented	800.20 FL	*800.20 FL	
8	1		*TAILGATE INNER RUBBER	Serviceable	368.90 FL	*- FL	
9	1		*REAR END PANEL OUTER	Repair	729.90 FL	*- FL	
10	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	78.10 FL	*78.10 FL	
11	1		*REAR BUMPER LOWER COVER	Serviceable	241.50 FL	*- FL	
12	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS	
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	5,846.40	4,392.30	
	- List Item Discount on L Items 25.00/25.00% (S\$)			1,451.60	1,088.08		
				Total Parts (S\$)	4,394.80	3,304.22	
	Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	TO REMOVE AND REFIX REAR BUMPER ASSY ,REFLECTORS ,RR MOULDINGS ,REFLECTORS ,TOP SPOILDER ,AUTO LOCK ASSY ,CUT ,WELD AND RENEW RR END PANEL OUTER ,KNOCK AND REPAIR RR FLOOR BOARD AND REALIGN TO SAME	New	800.00	580.00
3	PUTTY AND RESPRAY ON TAILGATE ,REAR FLOOR BOARD PANEL ,REAR END PANEL,REAR BUMPER AND REAR AFFECTED AREAS	New	1,000.00	800.00
4	TO REMOVE AND REFIX SEAT ,CARPET ,GARNISH TO FACILITATE ON REPAIRS	New	200.00	120.00
5	TO REMOVE AND REFIX REVERSE CAMERA AND REVERSE SENSOR AND RESET SYSTEM	New	100.00	60.00
6	RUSTPROOFING	New	60.00	30.00
	Gross Labou	ır Cost (S\$)	2,280.00	1,710.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >