



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SY 800B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,780.00	1,780.00
1	FRONT BUMPER LED DAYLIGHT W/CHROME LHS	CRACKED	328.00	328.00
1	FRONT BUMPER LED DAYLIGHT GRILLE COVER LHS	TWISTED	172.00	172.00
1	FRONT BUMPER CENTRE LOWER GRILLE (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER INNER FOAM COVER	TORN	112.00	112.00
2	FRONT BUMPER SIDE HOLDER RH & LH @ \$124.00	NOT NECESSARY	248.00	-
1	LHS FRONT HEADLAMP WASHER NOZZLE ASSY	NOT NECESSARY	598.00	-
1	LHS FRONT HEADLAMP WASHER NOZZLE COVER	MISSING	142.00	142.00
1	BONNET (NPA)	NOT NECESSARY	-	-
1	BONNET MERC. BADGE	NOT NECESSARY	72.00	-
1	FRONT CENTRE RADIATOR CHROME GRILLE	NOT NECESSARY	672.00	-
1	FRONT CENTRE RADIATOR CHROME GRILLE BADGE	NOT NECESSARY	98.00	-
1	LHS FRONT FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	LHS FRONT FENDER BLUE EFFECIENCY EMBLEM	NECESSARY	92.00	92.00
1	LHS FRONT FENDER LOWER CHROME MOULDING	NECESSARY	142.00	142.00
1	LHS HEADLAMP W/BALLAST	INNER HOLDER CRACKED	1,980.00	1,980.00
	LESS 10% DISCOUNT		-643.60	-474.80
			5,792.40	4,273.20
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE W/BASE (SN)	NOT NECESSARY	75.00	-
2	FRONT PDC SENSORS @ \$172.40 (SN)	NOT NECESSARY	344.80	-
			419.80	-
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF LHS FRONT FENDER.		800.00	250.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,000.00	400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND CHECK WIRING OF ALL ELECTRICAL COMPONENTS AND FOCUS HEADLAMP BEAM.		200.00	20.00
	TO CLEAR FAULT CODE WITH DIAGNOSTIC COMPUTER AND RESET TO SPECIFICATIONS.		350.00	80.00
			2,350.00	750.00
GRAND TOTAL			8,562.20	5,023.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS3/AIG20008082/Utd3s2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.