

S K AUTO CONSULTANTS

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference: TP/020/0108SK
Your Reference: TBA

Date: 11/8/2020

TO: LAU JUCT HUANG GERALDINE
C/o Asia Motor Sports Solution Pte Ltd
568 Geylang Road
Singapore 389514

Assessment of Vehicle No : SY 800B
Date of Accident : 23/07/2020
Date of Inspection : 04/08/2020

We have carried out a physical assessment of SY 800B at Asia Motor Sports Solution PL according to your instructions on 04/08/2020 and are pleased to submit our report as follows;

1.VEHICLE PARTICULARS

Registration No.	:	SY 800B
Make & Model	:	MERCEDES BENZ E250CGI
Year of Registration	:	25/1/2011
Engine Capacity (cc)	:	1796
Chassis No.	:	WDD2120472A359178
Engine No.	:	27186030163055-
Colour	:	Grey
Mileage (km)	:	157296

2.VEHICLE CONDITION

Body Paint:	:	Good
Steering	:	Serviceable
Foot Brake	:	Serviceable
Parking Brake	:	Serviceable

3.TYRE PARTICULARS & CONDITION

Front

RH Make/Size	:	Goodyear 245/45R17 - 50%
LH Make/Size	:	Goodyear 245/45R17 - 50%

Rear

RH Make/Size	:	Goodyear 245/45R17 - 50%
LH Make/Size	:	Goodyear 245/45R17 - 50%

Note: % denotes the remaining percentage of the tyre

2/5 4000
3275

S K AUTO CONSULTANTS

Page No. 2

Our Reference TP/020/0108SK
Vehicle No. SY 800B

4. DESCRIPTION OF DAMAGE

At the time of inspection observed that this vehicle had sustained damages to the Front Left side portion

Please see attached schedule for details.



Estimated Amount : S\$8,562.20
Adjusted Amount : S\$6,400/-
Estimated Repair Days* : 5 days
*(includes spray painting and complete work process)

Pursuant to your instruction, we have NOT AUTHORIZED repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 Days from the date hereof, this report shall be treated as correct

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by S K AUTO CONSULTANTS for any reliance on this report by any third party.

S K AUTO CONSULTANTS

Page No. 3

Our Reference TP/020/0108SK
Vehicle No. SY 800B

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	OUR ASSESSMENT(S\$)	
<u>PARTS (LIST ITEMS)</u>					
1	Front bumper	Deformed/Dmg.	1780.00	de 1780.00	✓
1	Front bumper LED daylight w/chrome LHS	Inner slot crk.	328.00	cm 328.00	✓
1	Front bumper LED daylight grille cover LHS	Inner side slot crk.	172.00	tm 172.00	✓
1	Front bumper centre lower grille	Reuse	0.00	nn 0.00	X
1	Front bumper inner foam cover	Cracked	112.00	Torn 112.00	✓
2	Front bumper side holder RH & LH @124.00	Necessary	248.00	nn 248.00	X
1	LHS Front headlamp washer nozzle assy	Cracked	598.00	nn 598.00	X
1	LHS Front headlamp washer nozzle cover	Missing	142.00	ms 142.00	✓
1	Bonnet	REPAIR/PAINT	0.00	nn 0.00	X
1	Bonnet MERC. Badge	Necessary	72.00	nn 72.00	X
1	Front centre radiator chrome grille	Inner holder crk.	672.00	nn 672.00	X
1	Front centre radiator chrome grille badge	Necessary	98.00	nn 98.00	X
1	LHS Front fender	REPAIR/PAINT	0.00	n 0.00	X
1	LHS Front fender BLUE EFFECIENCY emblem	Necessary	92.00	nn 92.00	✓
1	LHS Front fender lower chrome moulding	Necessary	142.00	nn 142.00	✓
1	LHS Headlamp w/ballast	Inner holder crk.	1980.00	1980.00	✓
			6436.00	6436.00	
			less 10%	10%	
			643.60	643.60	
			5792.40	5792.40	
<u>SPECIAL NETT ITEMS</u>					
1	Front number plate w/base	Dented	75.00	nn 50.00	X
2	Front PDC sensors @\$172.40	Damaged	344.80	nn 344.80	X
TOTAL PARTS			6212.20	6187.20	

4748
4273.2


S K AUTO CONSULTANTS

Page No. 4

Our Reference TP/020/0108SK

Vehicle No. SY 800B

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	800.00	600.00 — 250
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	800.00 ✓ 400
3	To remove and check wiring of all electrical components and focus headlamp beam	200.00	150.00 20
4	To clear fault code with diagnostic computer and reset to specifications	350.00	300.00 80
	Labour Total :	2350.00	1850.00
	TOTAL (PARTS & LABOUR):	8562.20	8037.20
Note: (For Lump Sum Repair) The workshop has agreed to undertake the repair on a Lump Sum Basis, and/or the use of ex stock/reconditioned parts whichever is possible (having taken into consideration to repair instead of replacements. The final adjusted Lump Sum contract amount is S\$6,400/-			



 S.Kumanan
 Motor Surveyor

750