

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20014413/KBA3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800042361

Claimant
Vehicle No : SHD5271K **Insured Vehicle No :** SLC3079X

Date of Loss: 03/12/2020 Nature of Claim: TP Claim No: 8592621267SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5271K		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B98851
Reg. Date:	25/01/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU003079117
Colour:	Metallic Pearl White/Red	Odometer:	224861 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,125.76	1,376.08	3,749.68	73.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,840.00	480.00	4,360.00	90.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,965.76	1,856.08	8,109.68	81.38
+ GST 7.00/7.00% (\$\$)	697.60	129.93	567.67	81.37
Nett Amount (\$\$)	10,663.36	1,986.01	8,677.35	81.38
+ Loss of Use (3.0 x S\$50.00/day) (\$\$)		150.00		
+ Car Rental (3.0 x S\$112.35/day) (\$\$)		337.05		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		2,480.55		
Global Sum Settlement (\$\$)		2,300.00		

INSPECTION

Date of Assignment: 04/12/2020

Date Inspected: 04/12/2020 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	442.61 FL	*442.61 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Cut	576.30 FL	*576.30 FL
4	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	15.40 FL	*- FL
5	1		*REAR BUMPER SIDE ,LH	Mtg Cracked	116.50 FL	*116.50 FL
6	1		*REAR BUMPER SIDE ,RH	Serviceable	117.70 FL	*- FL
7	1		*FILLER ,REAR BUMPER EXTENSION ,LH	Serviceable	123.70 FL	*- FL
8	1		*LENS AND BODY ,REAR LAMP ,LH	Serviceable	502.00 FL	*- FL
9	1		*LENS & BODY REAR COMBINATION LAMP ,LH	Serviceable	443.30 FL	*- FL
10	1		*LENS AND BODY ,REAR LAMP ,RH	Serviceable	502.00 FL	*- FL
11	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Serviceable	451.80 FL	*- FL
12	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
13	1		*LINER ,REAR WHEEL HOUSE ,LH	Serviceable	139.80 FL	*- FL
14	1		*COVER ,FLOOR UNDER ,NO.1 (LH)	Serviceable	175.10 FL	*- FL
15	1		*COVER ,FLOOR UNDER ,NO.2 (RH)	Serviceable	241.90 FL	*- FL
16	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
17	1		*SET PARKING AID	Dented	700.00 FS	*220.00 FS
18	1		*SET REAR BUMPER CLIP	Necessary	85.00 FS	*55.00 FS
19	1		*BUMPER CENTRE GUARD CLIP	Not Necessary	80.00 FS	*- FS
20	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
21	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
22	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
23	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
24	1		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,391.01	1,743.11
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,265.25	367.03
Total Parts (\$\$)	5,125.76	1,376.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
Gross Labour Cost (\$\$)			4,840.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >