



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2105354

INV Date 01/08/2021

Reference CC4/LPC20014414/Kga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 9072G
Insured Veh. GBJ 9230S
Claim No. 20/20/21/VC05/024038
Policy No. VC05/024038
Accident Date 19/12/2020
Inspection Date 20/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC20014414/Kga3q2 Date: 01/08/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 9230S	Veh. Inspected	GBJ 9072G	
Policy No.	VC05/024038	Coverage (\$)	0.00	
Claim No.	20/20/21/VC05/024038	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	23/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTFHT02P800249514	Colour	SILVER	
Odometer	53053 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	6 mm	
L/H Front Tyre	195 R15X8	MICHELIN	6 mm	
R/H Rear Tyre	195 R15X8	MICHELIN	6 mm	
L/H Rear Tyre	195 R15X8	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/12/2020	Inspection Date	20/01/2021	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 9072G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BUCKLED	373.02	373.02
6	REAR BUMPER CLIP @\$3.50	NECESSARY	21.00	21.00
1	REAR TAILGATE	BENT	2,162.00	2,162.00
1	TAILGATE LOGO	NECESSARY	81.60	81.60
1	TAILGATE INNER LOCK	TO REPAIR SEE LABOUR	301.70	-
1	LH TAILLAMP	CUT	256.90	256.90
1	REAR END PANEL OUTER	BENT	336.70	336.70
	LESS 25% DISCOUNT		-883.23	-807.80
			2,649.69	2,423.42
<u>SPECIAL NETT ITEMS</u>				
1	STICKER 70KM/HR (SN)	NECESSARY	10.00	10.00
1	REVERSE SENSOR (SN)	SCRATCHED	200.00	200.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	40.00	30.00
			290.00	280.00
<u>LABOUR</u>				
	REMOVE AND REFIX REAR WINDSCREEN GLASS .		100.00	100.00
	REMOVE & REFIX REAR BUMPER ASSY ,TAILGATE & ATTACHMENTS ,TAILLAMP,TO CUT ,WELD & RENEW REAR END PANEL OUTER ,KNOCKING & REPAIR REAR END PANEL INNER ,FLOORBOARD & REALIGN THE SAME .INCLUSIVE OF THE REPAIR OF TAILGATE INNER LOCK .		800.00	600.00
	PUTTY & RESPRAY REAR BUMPER ,TAILGATE ,REVERSE SENSORS ,REAR END PANEL OUTER & INNER ,FLOORBOARD & ALL AFFECTED AREAS .		800.00	600.00
	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION .		50.00	50.00
	RUSTPROOFING.		90.00	60.00
			1,840.00	1,410.00
GRAND TOTAL			4,779.69	4,113.42

Report Ref No. CC4/LPC20014414/Kga3q2



RECOMMENDED COST OF REPAIRS			4,113.42
-----------------------------	--	--	----------

Report Ref No. CC4/LPC20014414/Kga3q2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 9072G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 9072G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 9072G

RE-INSPECTION

