

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20014415/EPA3Q2  
**Date:** 07/07/2021**REFERENCE**

|                              |                                      |                             |               |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100473823-04 |
| <b>Claimant Vehicle No :</b> | SME5885A                             | <b>Insured Vehicle No :</b> | SLD9486J      |
| Date of Loss:                | 22/12/2020                           | Nature of Claim:            | TP            |
|                              |                                      | Claim No:                   | 3312205458SG  |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |             |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No:                     | <b>SME5885A</b>                   | Engine No:  | 4J11YT1364  |
| Make & Model:               | MITSUBISHI OUTLANDER, 2.0 (A)     | Chassis No: | GF7W0402229 |
| Reg. Date:                  | 27/08/2018 (Man. Year: 2018)      | Odometer:   | 67977 km    |
| Colour:                     | White                             |             |             |
| Engine Capacity:            | 1998 cc                           |             |             |
| Market Value/New Car Price: | N/A                               |             |             |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |             |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 225/55 R18 | Rear Tyre Size:  | 225/55 R18 |
| Front Left Side:  | Toyo 5 mm  | Rear Left Side:  | Toyo 5 mm  |
| Front Right Side: | Toyo 5 mm  | Rear Right Side: | Toyo 5 mm  |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 989.42            | 641.39            | 348.03            | 35.18         |
| Miscellaneous Items           | 0.00              | 0.00              | 0.00              |               |
| Labour                        | 2,260.00          | 1,010.00          | 1,250.00          | 55.31         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>3,249.42</b>   | <b>1,651.39</b>   | <b>1,598.03</b>   | <b>49.18</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b> | 227.46            | 115.60            | 111.86            | 49.18         |

|                                                             |                 |                 |                 |              |
|-------------------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| <b>Nett Amount (S\$)</b>                                    | <b>3,476.88</b> | <b>1,766.99</b> | <b>1,709.89</b> | <b>49.18</b> |
| <b>+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (S\$)</b> |                 | 385.20          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                               |                 | 2.00            |                 |              |
| <b>Nett Liability (S\$)</b>                                 |                 | <b>2,154.19</b> |                 |              |

INSPECTION

Date of Assignment: 23/12/2020

Date Inspected: 25/01/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)  
 209 Pandan Gardens  
 Singapore 609339

**Adjuster:** CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition     | Repairer's              | Amount               |
|-----|-----|----------|-------------------------------|---------------|-------------------------|----------------------|
| 1   | 1   |          | *SUNDRIES                     | Necessary     | 30.00 FS                | *20.00 FS            |
| 2   | 1   |          | *FACE ,RR BUMPER              | Cut           | 621.39 FS               | *621.39 FS           |
| 3   | 1   |          | *BRKT ,R/BMPR FACE SIDE ,RH   | Not Necessary | 9.24 FS                 | *- FS                |
| 4   | 1   |          | *REINFORCEMENT ,RR BUMPER ,RH | Not Necessary | 60.83 FS                | *- FS                |
| 5   | 1   |          | *EXTENSION ,RR BUMPER         | Not Necessary | 178.64 FS               | *- FS                |
| 6   | 8   |          | *CLIPS ,END ROOM COVER        | Not Necessary | 12.32 FS                | *- FS                |
| 7   | 1   |          | *REFLECTOR ,TAIL LAMP ,RH     | Not Necessary | 77.00 FS                | *- FS                |
|     |     |          |                               |               | <b>Total Parts (\$)</b> | <b>989.42 641.39</b> |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                 | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-----------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                                             |          |                 |                 |
| 1                              | RENEW RR BUMPER                                                             | New      | 1,350.00        | 450.00          |
| 2                              | RESPRAY RR BUMPER & RHR FENDER                                              | New      | 700.00          | 350.00          |
| 3                              | CHECK WIRING ELECTRICAL SYSTEM                                              | New      | 30.00           | 30.00           |
| 4                              | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New      | 120.00          | 120.00          |
| 5                              | REMOVE & REFIT REVERSE SENSOR                                               | New      | 60.00           | 60.00           |
| <b>Gross Labour Cost (S\$)</b> |                                                                             |          | <b>2,260.00</b> | <b>1,010.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >