

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20014416/UBA3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0006160_01

Claimant Vehicle No : GBD8217U Insured Vehicle No : PC7736J

Date of Loss: 15/12/2020 Nature of Claim: TP Claim No: MFL2020D0002706

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD8217U**

Make & Model: TOYOTA HIACE, 3.0 D DX DIESEL TURBO MT 2WD LGV (M) Engine No: 1KD2499998

Reg. Date: 25/05/2015 (Man. Year: 2015) Chassis No: KDH2010162781

Colour: Silver Odometer: 131129 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15 Rear Tyre Size: 195R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,544.75	3,212.82	2,331.93	42.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	980.00	1,680.00	63.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,204.75	4,192.82	4,011.93	48.90
Approved Total (Overridden) (S\$)		3,350.00		
Nett Amount (S\$)	8,204.75	3,350.00	4,854.75	59.17
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,886.45		
Global Sum Settlement (S\$)		3,700.00		

INSPECTION

Date of Assignment: 23/12/2020

Date Inspected: 24/12/2020 Inspected At: Ping Motor Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, #01-25
Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Feb 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 D DX DIESEL TURBO MT 2WD LGV (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD8217U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR LH	Badly Dented	1,620.00 FL	*1,415.20 FL
2	1	*FRONT DOOR SIDE MIRROR LH	Broken	585.00 FL	*480.50 FL
3	1	*FRONT DOOR WINDOW OUTER MOULDING LH	Cut	90.00 FL	*90.00 FL
4	1	*FRONT DOOR WINDOW REGULATOR LH	Serviceable	350.00 FL	*- FL
5	1	*FRONT DOOR WINDOW REGULATOR MOTOR LH	Shorted / Jammed	330.00 FL	*330.00 FL
6	1	*FRONT DOR MECHANISM LOCK LH	Not Necessary	380.00 FL	*- FL
7	1	*FRONT DOOR LOCK STRIKER LH	Not Necessary	55.00 FL	*- FL
8	1	*FRONT DOOR INNER TRIM BOARD LH	Deformed / Torn	710.00 FL	*544.10 FL
9	2	*FRONT DOOR HINGE U/L (LH)	Not Necessary	178.00 FL	*- FL
10	1	*FRONT DOOR CHECKER LH	Not Necessary	160.00 FL	*- FL
11	1	*FRONT DOOR OUTER WEATHERSTRIP	Not Necessary	190.00 FL	*- FL
12	1	*FRONT DOOR LOWER STEP GARNISH LH	Cut	185.00 FL	*185.00 FL
13	1	*FRONT WHEEL COVER LH	Repair	280.00 FL	*- FL
14	1	*FRONT BUMPER	Cut	550.00 FL	*525.10 FL
15	1	*FRONT BUMPER SIDE RETAINER LH	Not Necessary	120.00 FL	*- FL
16	1	*FRONT HEADLAMP LH	Scratched	680.00 FL	*607.20 FL
17	1	*FRONT TOP CORNER PANEL LH	Repair	230.00 FL	*- FL
18	1	*FRONT TOP CORNER PANEL SIDE MIRROR LH	Not Necessary	220.00 FL	*- FL
19	1	*FRONT TYRE LH	Not Necessary	280.00 FS	*- FS
20	1	*FRONT DOOR COMPANY STICKER	Necessary	20.00 FS	*20.00 FS
21	1	*FRONT DOOR INNER TRIM BOARD CLIP	Necessary	30.00 FS	*30.00 FS
22	1	*FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,273.00	4,257.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,728.25	1,044.28
Total Parts (\$\$)	5,544.75	3,212.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRINGS	New	80.00	20.00
2	TO TUFF COAT AFFECTED AREA	New	200.00	30.00
3	TO TRANSFER FRONT DOOR COMPONENT FROM OLD TO NEW	New	180.00	60.00
4	TO CONDUCT WHEEL ALIGNMENT	New	200.00	0.00
5	TO STRAIGHTEN,REPAIR ,REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	450.00
6	TO SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	420.00
Gross Labour Cost (\$\$)			2,660.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >