

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20014417/EEA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070104189
Claimant Vehicle No :	YL1978M	Insured Vehicle No :	SGD7088Y
Date of Loss:	15/12/2020	Nature of Claim:	TP
		Claim No:	8749188199SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YL1978M	Engine No:	4HG1916772
Make & Model:	ISUZU NPR71L, 4.6 D (M)	Chassis No:	JAANPR71L27102480
Reg. Date:	27/08/2002 (Man. Year: 2002)	Odometer:	439823 km
Colour:	White		
Engine Capacity:	4570 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.50 -16	Rear Tyre Size:	7.50 -16
Front Left Side:	Track King 4 mm	Rear Left Side:	Track King 4 mm
Front Right Side:	Track King 4 mm	Rear Right Side:	Track King 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,750.00	10,400.00	1,350.00	11.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	3,600.00	650.00	15.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	16,000.00	14,000.00	2,000.00	12.50
+ GST 7.00/7.00% (\$\$)	1,120.00	980.00	140.00	12.50
Nett Amount (\$\$)	17,120.00	14,980.00	2,140.00	12.50
+ Loss of Use (20.0 x S\$100.00/day) (\$\$)		2,000.00		
Nett Liability (\$\$)		16,980.00		
Global Sum Settlement (\$\$)		16,900.00		

INSPECTION

Date of Assignment:	23/12/2020		
Date Inspected:	30/12/2020	Inspected At:	Jin Quan Engineering Pte Ltd (HQ) 28 Jalan Buroh Singapore 619484
Estimated Period of Repair:	15.0 days		

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ALLUMINIUM SIDE COVER	Dented	2,200.00 F	*1,800.00 F
2	1		*ALLUMINIUM FRAME	Dented	1,600.00 F	*1,400.00 F
3	1		*ALLUMINIUM CROSS MEMBER	Dented	3,800.00 F	*3,500.00 F
4	2		*STOPPER	Dented	3,600.00 F	*3,300.00 F
5	1		*TMA LOGO AND STICKER 1 SET	Necessary	550.00 F	*400.00 F
F=Franchise part.						
Total Parts (S\$)					11,750.00	10,400.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PROVIDE MANPOWER TO SPRAY PAINTING	New	800.00	600.00
2	LABOUR CHARGE TO PANEL BEATING, REPAIR AND WELDING TMA INCLUDE INSTALLATION OF ABOVE PARTS	New	3,450.00	3,000.00
Gross Labour Cost (\$\$)			4,250.00	3,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >