

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20014419/R1QD3E2

**Date:** 06/09/2021

### REFERENCE

Insured/Claimant:	TAN JIAN YUAN(CHEN JIANYUAN)	Policy No:	1900235871	
Date of Loss:	22/12/2020	Nature of Claim:	OD	Claim No: 5055692097SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ7945X	Engine No:	CHZC35581
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Chassis No:	WAUZZZGA2LA000982
Reg. Date:	31/10/2019 (Man. Year: 2019)	Odometer:	16316 km
Colour:	Grey		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$104,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,346.00	22,193.12	15,152.88	40.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	27,392.00	13,292.00	14,100.00	51.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>64,738.00</b>	<b>35,485.12</b>	<b>29,252.88</b>	<b>45.19</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>63,938.00</b>	<b>34,685.12</b>	<b>29,252.88</b>	<b>45.75</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>4,475.66</b>	<b>2,427.96</b>	<b>2,047.70</b>	<b>45.75</b>
<b>Nett Amount (S\$)</b>	<b>68,413.66</b>	<b>37,113.08</b>	<b>31,300.58</b>	<b>45.75</b>

### INSPECTION

Date of Assignment: 24/12/2020

Date Inspected: 23/12/2020 Inspected At:

24 Benoi Sector

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 19.0 days

**Adjuster:** MOHD RASUL

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,854.00 FS	*1,482.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	343.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Deformed	195.00 FS	*155.60 FS
4	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Cracked	334.00 FS	*267.20 FS
5	1		*FRONT BUMPER END CAP - LH / RH	O/S Scratched/N/S Serviceable	68.00 FS	*26.72 FS
6	1		*FRONT BUMPER SPOILER	Cut	296.00 FS	*236.40 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	154.00 FS	*122.80 FS
8	2		*WHEEL SPOILER - LH / RH	Serviceable	68.00 FS	*- FS
9	1		*FRONT BUMPER ADAPTER - LH	Serviceable	35.00 FS	*- FS
10	1		*FRONT BUMPER ADAPTER - RH	Deformed	42.00 FS	*33.20 FS
11	1		*RADIATOR GRILLE	Cracked	1,395.00 FS	*1,116.00 FS
12	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	123.00 FS	*98.00 FS
13	1		*FRONT BUMPER CARRIER	Bent	679.00 FS	*543.20 FS
14	1		*FRONT BUMPER TOP COVER	Deformed	99.00 FS	*79.04 FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	77.00 FS	*61.20 FS
16	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Serviceable	70.00 FS	*- FS
17	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
18	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
19	1		*HORN - LH LOW TORN	Serviceable	283.00 FS	*- FS
20	1		*SIGNAL HORN - RH HIGH TONE	Cracked	180.00 FS	*143.60 FS
21	1		*SPRING SHACKLE - LH / RH	N/S Bent / O/S Serviceable	62.00 FS	*24.80 FS
22	2		*FRONT FENDER - LH / RH	Bent	2,268.00 FS	*1,814.40 FS
23	1		*FRONT FENDER ATTACHMENT PARTS LH	Not Necessary	40.00 FS	*- FS
24	1		*FRONT FENDER BRACKET - LH / RH OUTER	N/S Necessary/O/S Serviceable	32.00 FS	*12.16 FS
25	1		*FRONT FENDER BRACKET - LH / RH MIDDLE	N/S Necessary/O/S Serviceable	94.00 FS	*74.56 FS
26	1		*FRONT FENDER BRACKET - LH / RH INNER	N/S Necessary/O/S Serviceable	32.00 FS	*12.16 FS
27	2		*FRONT FENDER BRACE - LH / RH	Bent	74.00 FS	*57.76 FS
28	1		*FRONT FENDER CLOSING ELEMENT - LH / RH	N/S Cracked/O/S Serviceable	66.00 FS	*25.92 FS
29	1		*FRONT FENDER INSULATION - LH / RH	N/S Necessary/O/S Serviceable	152.00 FS	*60.08 FS
30	2		*FRONT FENDER BRACKET - INNER UPPER / LOWER	Serviceable	46.00 FS	*- FS
31	2		*WHEEL HOUSING LINER - LH / RH	Serviceable	388.00 FS	*- FS
32	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Serviceable	57.00 FS	*- FS
33	1		*BONNET	Bent	2,757.00 FS	*2,205.60 FS
34	1		*BONNET ATTACHMENT PARTS	Necessary	163.00 FS	*117.60 FS
35	2		*BONNET LID HINGE - LH / RH	Bent	122.00 FS	*96.48 FS
36	1		*BONNET GAS FILLED STRUT	Serviceable	101.00 FS	*- FS
37	2		*BONNET STRIKER - LH / RH	Bent	218.00 FS	*173.60 FS
38	1		*BONNET SOUND ABSORBER	Serviceable	217.00 FS	*- FS
39	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	30.00 FS	*23.36 FS
40	1		*BONNET IMPACT PROTECTION - LH	Necessary	30.00 FS	*23.76 FS
41	1		*BONNET IMPACT PROTECTION - RH	Necessary	30.00 FS	*23.36 FS
42	2		*TOP FENDER LEDGE COVER - LH / RH UPPER	Serviceable	82.00 FS	*- FS
43	2		*TOP FENDER LEDGE COVER - LH / RH LOWER	Cracked	32.00 FS	*24.32 FS
44	1		*PLENUM CHAMBER COVER	Serviceable	156.00 FS	*- FS
45	2		*BONET LID LOCK	Bent	423.00 FS	*338.40 FS
46	1		*BONNET BOWDEN CABLE - CENTRE	Cut	57.00 FS	*45.52 FS
47	1		*BONNET LID LOCK CABLE	Serviceable	73.00 FS	*- FS
48	1		*BONNET RELEASE ELEMENT	Cut	57.00 FS	*45.52 FS
49	2		*BONNET BOWDEN CABLE - LH / RH	Serviceable	114.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*BONNET RELEASE LEVER	Serviceable	13.00 FS	*- FS
51	2		*HEADLIGHT MOUNTING - LH / RH	Cracked	234.00 FS	*187.20 FS
52	2		*LED HEADLIGHT - LH / RH	Cracked	9,718.00 FS	*3,887.20 FS
53	2		*LIFT CYLINDER - LH / RH	Cracked	282.00 FS	*112.40 FS
54	1		*LIFT CYLINDER HOSE	Cut	175.00 FS	*140.00 FS
55	1		*HEADLIGHT WASHER PUMP	Serviceable	151.00 FS	*- FS
56	1		*WINDSCREEN WASHER SYSTEM PUMP	Serviceable	121.00 FS	*- FS
57	1		*WASH WATER RESERVOIR	Deformed	173.00 FS	*138.40 FS
58	2		*FRONT WHEEL COVER - LH / RH	O/S Missing / N/S Necessary	636.00 FS	*508.80 FS
59	1		*LOCK CARRIER	Cracked	983.00 FS	*786.40 FS
60	1		*AIRCON CONDENSER	Bent	545.00 FS	*436.00 FS
61	1		*REFRIGERANT LINE	Serviceable	619.00 FS	*- FS
62	1		*REFRIGERANT LINE	Serviceable	476.00 FS	*- FS
63	1		*EXTERNAL TEMPERATURE SENSOR	Serviceable	56.00 FS	*- FS
64	1		*ADDITIONAL RADIATOR	Bent	859.00 FS	*687.20 FS
65	1		*RADIATOR	Bent	941.00 FS	*752.80 FS
66	2		*RADIATOR BRACKET - UPPER	Cracked	79.00 FS	*62.88 FS
67	2		*RADIATOR BUSH - LOWER	Missing	19.00 FS	*14.72 FS
68	1		*READY MIX COOLANT	Necessary	177.00 FS	*141.44 FS
69	2		*RADIATOR SEALING STRIP - LH / RH	Not Necessary	36.00 FS	*- FS
70	1		*RADIATOR FAN	Scratched	1,191.00 FS	*1,012.00 FS
71	2		*RADIATOR AIR GUIDE - LH / RH	Cracked	60.00 FS	*47.84 FS
72	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Cracked	22.00 FS	*17.20 FS
73	2		*WINDOW APERTURE SEAL - LH / RH OUTER	Not Necessary	268.00 FS	*- FS
74	1		*AIR INTAKE AIR GUIDE	Serviceable	54.00 FS	*- FS
75	1		*AIR INTAKE COVER	Serviceable	28.00 FS	*- FS
76	1		*AIR INTAKE AIR GUIDE - OUTER	Cracked	64.00 FS	*50.80 FS
77	1		*AIR INTAKE AIR GUIDE - INNER	Serviceable	19.00 FS	*- FS
78	1		*AIR INTAKE WATER DRAINAGE HOSE	Serviceable	32.00 FS	*- FS
79	1		*AIR INTAKE AIR FILTER	Serviceable	267.00 FS	*- FS
80	1		*AIR INTAKE MANIFOLD	Serviceable	134.00 FS	*- FS
81	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
82	1		*SUNDRIES	Necessary	300.00 FS	*155.12 FS
83	1		*FRONT CHASSISFRAME COVER PLATE - LH (Supplementary)	Bent	91.00 FS	*72.72 FS
84	1		*FRONT HEADLIGHTS COMPENSATING PIECE (Supplementary)	Cracked	45.00 FS	*35.76 FS
85	1		*MECHATRONIC (Supplementary)	Bent	4,008.00 FS	*3,206.40 FS
86	1		*TRANSMISSION FLUID (Supplementary)	Necessary	120.00 FS	*99.04 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 37,346.00 22,193.12**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	280.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
3	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNITS AND POWER MODULES	New	800.00	250.00
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY	New	800.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,400.00	3,250.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH UPPER A PILLARS AND BOTH FRONT DOORS	New	7,700.00	3,300.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER (Supplementary)	New	800.00	800.00
9	TO PUT THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR (Supplementary)	New	1,800.00	1,800.00
10	TO REMOVE AND REINSTALL THE FRONT SUSPENSION WHEEL ASSY TO FACILITATE THE REPAIR. (Supplementary)	New	2,400.00	0.00
11	TO REMOVE AND REINSTALL ENGINE ASSY AND GEARBOX ASSY TO FACILITATE THE REPAIR. (Supplementary)	New	2,800.00	0.00
12	TO RENEW GEARBOX MECHATRONIC AND CARRY OUT ADAPTATION (Supplementary)	New	980.00	980.00
13	TO CARRY OUT WHEEL ALIGNMENT TEST (Supplementary)	New	240.00	240.00
14	TO ALIGN AND REPAIR FRONT BOTH CHASSIS FRAMES. (Supplementary)	New	800.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>27,392.00</b>	<b>13,292.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >