

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014421/KTD3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00119052000

**Claimant
Vehicle No :** SKX6483T

**Insured
Vehicle No :** SKF867D

Date of Loss: 22/12/2020

Nature of
Claim: TP

Claim
No: SNM20D204983/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX6483T**

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: L15B4022872

Reg. Date: 22/12/2015 (Man. Year: 2015)

Chassis No: RU11102862

Colour: Metallic Black

Odometer: 122464 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size: 215/60R16

Front Left Side: Dunlop 4 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 4 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,582.24	2,560.44	1,021.80	28.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,650.00	690.00	29.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,922.24	4,210.44	1,711.80	28.90
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	5,922.24	3,350.00	2,572.24	43.43
+ GST 7.00/7.00% (S\$)	414.56	234.50	180.06	43.43
Nett Amount (S\$)	6,336.80	3,584.50	2,752.30	43.43

INSPECTION

Date of Assignment: 24/12/2020

Date Inspected: 24/12/2020 Inspected At:

Ah Lim Motor Company (Sin Ming)
176 Sin Ming Drive #05-12, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX6483T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	972.40 FL	*972.40 FL
2	1		*VEZEL BADGE	Necessary	45.80 FL	*45.80 FL
3	1		*TAILGATE INNER TRIM BOARD	Serviceable	183.50 FL	*- FL
4	1		*TAILGATE INNER LOCK	Repair	136.20 FL	*- FL
5	1		*REAR BUMPER	Bent	777.90 FL	*777.90 FL
6	10		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
7	1		*TAIL END PANEL	Bent	415.60 FL	*415.60 FL
8	1		*TAIL END PANEL INNER TRIM BOARD	Mtg Distorted	66.60 FL	*66.60 FL
9	1		*SPARE TIRE PANEL	Repair	835.30 FL	*- FL
10	1		*RR END BUZZER	Cracked	110.10 FL	*110.10 FL
11	1		*RR END KEY ANTENNA	Serviceable	58.10 FL	*- FL
12	1		*RR SPARE TYRE INNER BOX	Cracked	167.50 FL	*167.50 FL
13	1		*REAR WINDSCREEN MOULDING	Necessary	138.60 FL	*138.60 FL
14	1		*SPARE TYRE PANEL UNDER COST	Buckled	118.30 FL	*118.30 FL
15	1		*TAILGATE WEATHER STRIP (50%)	Distorted/Dented	83.52 FS	*52.20 FS
16	1		*SET REVERSE SENSOR	Cracked	220.00 FS	*200.00 FS
17	2		*SET WINDSCREEN SEALANT	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,394.42	3,130.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	812.18	569.56
Total Parts (\$\$)	3,582.24	2,560.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND INSTALL REVERSE SENSOR	New	30.00	30.00
2	TO DISMANTLE AND INSTALL REAR WINDSCREEN	New	120.00	120.00
3	TO DISMANTLE AND INSTALL TAILGATE,TRANSFER TAIL GATE INNER PARTS AND WIRING HARNESS	New	70.00	60.00
4	TO DISMANTLE AND INSTALL RR LUGGAGE COMPARTMENT INNER BOX AND TRIM COVER	New	70.00	60.00
5	TO DISMANTLE AND INSTALL DAMAGE PARTS TO CUT,KNOCK AND WELD TAIL END PANEL AND TO KNOCK AND REPAIR SPARE TYRE PANEL AND AFFECTED AREA	New	1,200.00	700.00
6	TO SPRAY TAIL GATE,TAIL END PANEL,SPARE TIRE AND RESEAL END PANEL AND SPARE TIRE PANEL	New	850.00	680.00
Gross Labour Cost (\$\$)			2,340.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >