1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0014423/kg
ASS	IGNMENT
From: Date:	Veh No: GR 687R Yr Regn: 04, 1
Estimated Cost:	Type: M.Car / M.Cycle / Bus (Van Phorry / Taxi / Prime Mover /
OD TP WS ITP RES ! OD RES ! EVA ! INV ! MY	Truck / Trailer or
To Inspect Vehicle No:	Make: NIS NV350 c.c 248
at Workshop m/s Gvan Motar	Colour Pilm A/C: Insured / Std / NI / NJ
of a second seco	Sp.Reading 192727 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: JNIMCZE267 000187
Claims No. CMTD2003780/RUC	Gen. Cond: Good) Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inerder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: MIT I SIRIM I STD AIRIM or
60 1 Rear traperson or a	Tyre Size: F: 185R 15 X8
(Pollcy Condition)	R:
Pemark: The veh had commenced its N/S O/S	STOUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 9 mm R/Bal. 9 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 9 mm L/Bal. 59 inm
Est. Repairs: O6 days Res.: Yes or No	D.O.A. 21/12/20 D.O.I. 24/12/20
Est. Repairs: 76 days Res.: Yes or No Lum Sum: 26 % 3 Val.: Yes or No	Survey held at
Lum Sum: 26 % 3 Val.: Yes or No CA / REV / REP. / 24 HRS	1 1 20
Lum Sum: 20 % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or
Lum Sum: 20 % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	Survey held at
Lum Sum: 26 % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Vehicle: IN / OUT  Date / Time   Action / Instruction	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.
Lum Sum:  20 % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Vehicle: IN / OUT  Date:Person Contacted:  Date / Time   Action / Instruction  0/12/20@3.08pm revised to Ruth Chua by em	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.
Lum Sum: 26 % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Vehicle: IN / OUT  Date / Time   Action / Instruction	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.
Lum Sum: 26 % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction  0/12/20@3.08pm revised to Ruth Chua by em	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.
Lum Sum: 26 % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction  0/12/20@3.08pm revised to Ruth Chua by em	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.
Lum Sum: 26 % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction  0/12/20@3.08pm revised to Ruth Chua by em	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.
Lum Sum: 26 % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction  0/12/20@3.08pm revised to Ruth Chua by em	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.
Lum Sum:    26 % 3 Val.: Yes or No	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.  ail.  3125.59, 36%)
CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time Action / Instruction  C/12/20@3.08pm revised to Ruth Chua by em  Kenneth confirmed LS \$5600 (Red \$	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.  ail.  3125.59, 36%)
Lum Sum:    26 % 3 Val.: Yes or No	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.  ail.  3125.59, 36%)  Bys Of Repair: 6  Survey No. of Trip: 1 Survey Fee:
Lum Sum:    20 % 3 Val.: Yes or No	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.  ail.  3125.59, 36%)  Bys Of Repair: 6  Survey Fee:   Transportative:   Transportati
Lum Sum:    26 % 3 Val.: Yes or No	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.  ail.  3125.59, 36%)  Bys Of Repair: 6  Survey No. of Trip: 1 Survey Fee:    Transportation:   See   S
CA / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time   Action / Instruction  O/12/20@3.08pm revised to Ruth Chua by em  Kenneth confirmed LS \$5600 (Red \$  EVENUE Pass to? Prell. Report Press to Press	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop of  The U/C   Chassis frame   Body Structure affected due to collision.  ail.  3125.59, 36%)  ays Of Repair: 6  Survey No. of Trip: 1 Survey Fee:  Transportative:  Site Insp (\$ ) \$ - RS_S!  Interview (\$ ) First
Lum Sum:    20 % 3 Val.: Yes or No	Survey held at  Des. of Damages: Frt   Rear   O/S   N/S   U/C   Rooftop or  The U/C   Chassis frame   Body Structure affected due to collision.  ail.  3125.59, 36%)  Bys Of Repair: 6  Survey No. of Trip: 1 Survey Fee:    Transportation:   See   S

## 源摩哆廠 **GUAN MOTOR WORKS**

Not Norhanise Clam & Resurry After Paint 6453 8292 H/P: 9742 6003 Galay

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 I-VP: 9742 6003

### **REPAIR ESTIMATE FOR GR687R**

No.	Qty				
4	<u>List Items</u> 1 Rear bumper		\$	B1 660.50 -	ę.
1 2	<ol> <li>Rear bumper</li> <li>Rear bumper side repainer</li> </ol>		\$	011 60.00 -	
	1 Rear bumper inner step/reinforcem	ent	Ś	289.50	
3	1 set Rear bumper clips	ent	ζ	Ma 40.00 -	
4	2 Taillamp		Š	417.80 7	
5	1 Rear tailgate		\$ \$ \$	م 1,742.00 س	
6 7	1 Rear tailgate outer chrome handle		\$	Sa 221.40 X	
8	1 Rear tailgate centre "NISSAN" logo		\$	m 89.30 -	
9	1 Rear tailgate LH "NV350" emblem		Š,	ha 101.30 -	
10	1 Rear tailgate LH "URVAN" emblem	A T	\$ 1	m 59.70 —	
11	1 Rear tailgate windscreen glass	Shotter	مع	937.00	- North
12	1 Rear tailgate top lock		\$	AN 261.00 -	
13	1 Rear tailgate lower lock catch		\$	1 48.80 X	
14	_	The	\$	292.30	
15	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		\$	<b>127.50</b> ∧	1
16			\$	237.80 X	
17	1 set Rear tailgate inner board clips		100	rac 60.00 -	
18	1 Rear end panel inner	onto hanna - life	_	461.60	
19	1 Rear end panel outer the Repairer of the	f - 11 1	\$	<b>4</b> 247.60 —	
	10 resurvey before/at	tter spray painting	\$	6,295.10	
	To display damaged       Parts prices are subjections	part(s) durin <b>gess</b> in1.0%	\$	629.51	
	• Third party survey is	on a "Without Prejudice" bast	\$	5,665.59	
	No illegal modification	n(s) is allowed			
	Special Nett Items lementary item(s	s) must be resurveyed and	,	hars 250.00 200	
20	T 26f Weverage actions			50.00 X	·~
21	1 Rear number plate Acknowledged by Repa	irer	\$	1er 80.00 400	lati
22	1 set Rear windscreen sea fantiure:		\$	ver 80.00 301	بر م
23	1 set Rear end panel sealande:		\$	15.00 /Z	Ca
24	1 Rear tailgate RH "8pax" sticker		ç	Ma 15.00 12 5	
25	1 Rear tailgate LH "70km/h" sticker	Total:	\$	490.00	~
		Total:	<del>&gt;</del>	450.00	
Selection of	<u>Labour</u>	hualding and	\$	1,000.00	11
1	Labour Charges for remove/refit, cutting/	weiding and	ð	1,000.00	7
18 1	replacement of damages.		خ	1,000.00 \$	e1
2	To putty and spray Spray Paintings charge	!S.	\$	140.00 124	
3	To remove, refit rear windscreen glass.		\$	40.00 20	
4	To check wirings and lightings.		\$	80.00 <b>5</b> 0	
5	To remove, refit reverses sensors.		\$ !	80.00	4
6	To remove, refit rear tailgate fittings.		\$		
7	To remove, refit rear upholstery and attac	inments.	\$	150.00	7
8	To supply and apply anti rust treatment	11 / 11 .	\$	80.00	(
		Total:	\$	2,570.00	
	Total Pa	rts and Labour:	\$	8,725.59	

# **SINGAPORE ACCIDENT STATEMENT**

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate o. minimation provided mask to 30 december 20 december

#### The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies. Any false reporting may be referred to the Police for investigation. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid. ACCIDENT STATEMENT 22/12/2020 11:45 (SGT) Date of Submission 21/12/2020 17:28 (SGT) Date of Accident Ang Mo Kio Ave 5, Singapore Exact Location of Accident ..... TOWARDS CITY (NOVENA) Additional Location Information Singapore Country/State of Loss ..... DETAILS OF OWN VEHICLE **GR687R** Vehicle Registration Number ..... INSURED/POLICYHOLDER Is company? NEW PLUMBING SERVICES PTE. LTD. Name Of Registered Owner Company Reg No 2XXXX003D NPSPL7797@GMAIL.COM

Email Address (Phone) +65-64547797 Mobile Phone No ..... (Office) +65-64547797 Alternative Phone No .....

VEHICLE PARTICULARS

Nissan Manufacturer ..... Nv350 Model ..... Exact purpose for which vehicle was being used at time of **Employment** accident ..... Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? ..... Commercial vehicle Vehicle Category .....

INSURANCE COMPANY

Liberty Insurance Name of Insurance Company ..... Type of Coverage ..... Comprehensive Fleet Policy ..... SD20V03029 /VCV /R00 Policy Number ..... Cover Note Number .....

ANKUSAMY BALUSAMY Name of Driver GXXXX351P Passport No/FIN Date Of Birth 15/03/1988 Occupation ..... Outdoor

C Accident report SS2120CM0002

Page 1 of 17

Date Of Driving Pass

Driving experience

Gender Mobile Number

Alt. Phone Number
Email Address

Address .....

Address complement ....

### DETAILS OF OTHER VEHICLE PROPERTY 1

Yes

No No

21/08/2017

3 YEARS AND 4 MONTHS

NPSPL7797@GMAIL.COM

7030 ANG MO KIO AVENUE 5 #05-07 NORTHSTAR @ AMK

(Phone) +65-90454760

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Passport No/FIN

YP1564C

Commercial Colour

Commercial vehicle

KOLANJI PRAKASH

0XXXX7277

Are accident photos available for attachment?

Was there any video captured by Car Camera? .....

Was there any audio recorded? .....

Accident report SS2120CM0002

Page 2 of 17

SK	FTC	H.	DI	1	N

Ang me	kio Ave-5
B	
- CAR 687R - YP 1564C	ind payk - 2
	28 Pm I go kng mo kio Ave -5
	Square my van ( ) CTR 687 R my front
my van behi	
OR 687R ber	aind damage
age of a second	
The second secon	have the control of the state of the control of the
grand and the same of Andrews	tripodenja u počini ištope žiplinjih po stariju, endomine i ligi savaje. Pri
and the second second	
A STATE OF THE STA	
DECLARATION  /We declare the foregoing particula	ers are true in every respect.
QUICES PTE	A. Baugamey
Policy of der's Signo Une	Driver's Signature (If driver is not the policyholder)  Name:  Name: