



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GR 687R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	BENT	660.50	660.50
2	REAR BUMPER SIDE REPAIRER	DISTORTED	60.00	60.00
1	REAR BUMPER INNER STEP/REINFORCEMENT	BENT	289.50	289.50
1	SET REAR BUMPER CLIPS	NECESSARY	40.00	40.00
2	TAILLAMP	MTG CRACKED	417.80	417.80
1	REAR TAILGATE	BENT	1,742.00	1,742.00
1	REAR TAILGATE OUTER CHROME HANDLE	SERVICEABLE	221.40	-
1	REAR TAILGATE CENTRE "NISSAN" LOGO	NECESSARY	89.30	89.30
1	REAR TAILGATE LH "NV350" EMBLEM	NECESSARY	101.30	101.30
1	REAR TAILGATE LH "URVAN" EMBLEM	NECESSARY	59.70	59.70
1	REAR TAILGATE WINDSCREEN GLASS	SHATTERED	937.00	937.00
1	REAR TAILGATE TOP LOCK	DENTED	261.00	261.00
1	REAR TAILGATE LOWER LOCK CATCH	TO REPAIR SEE LABOUR	48.80	-
1	REAR TAILGATE CENTRAL LOCK	JAMMED	292.30	292.30
1	REAR TAILGATE INNER TRIM BOARD	SERVICEABLE	237.80	-
1	SET REAR TAILGATE INNER BOARD CLIPS	NECESSARY	60.00	60.00
1	REAR END PANEL INNER	BENT	461.60	461.60
1	REAR END PANEL OUTER	BENT	247.60	247.60
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	127.50	-
	LESS 10% DISCOUNT		-635.51	-571.96
			5,719.59	5,147.64
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REVERSE SENSORS (SN)	SHORTED	250.00	200.00
1	REAR NUMBER PLATE (SN)	SERVICEABLE	50.00	-
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR END PANEL SEALANT (SN)	NECESSARY	80.00	30.00
1	REAR TAILGATE RH "8 PAX" STICKER (SN)	NECESSARY	15.00	12.00
1	REAR TAILGATE LH "70KM/H" STICKER (SN)	NECESSARY	15.00	12.00
			490.00	294.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES TO REMOVE/REFIT,CUTTING/WELDING AND REPLACEMENT OF DAMAGES.INCLUSIVE OF THE REPAIR OF REAR TAILGATE LOWER LOCK CATCH.		1,000.00	600.00
	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES.		1,000.00	700.00
	TO REMOVE,REFIT REAR WINDSCREEN GLASS.		140.00	120.00
	TO CHECK WIRINGS AND LIGHTINGS.		40.00	20.00
	TO REMOVE,REFIT REVERSE SENSORS.		80.00	50.00
	TO REMOVE,REFIT REAR TAILGATE FITTINGS.		80.00	60.00
	TO REMOVE,REFIT REAR UPHOLSTERY AND ATTACHMENTS.		150.00	60.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.		80.00	60.00
			2,570.00	1,670.00
	<b>GRAND TOTAL</b>		<b>8,779.59</b>	<b>7,111.64</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,600.00</b>

Report Ref No. CS/SMO20014423/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.