



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 7220L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRT BONNET (WCP)	DENTED	550.00	550.00
1	FRT GRILLE (WCP)	CRACKED	230.00	230.00
4	FRT GRILLE CLIP (WCP)	NOT NECESSARY	8.00	-
1	FRT BUMPER (AGENT) (WCP)	DISTORTED	470.00	470.00
1	FRT BUMPER RETAINER RH (WCP)	BENT	12.00	12.00
10	FRT BUMPER CLIP (WCP)	NECESSARY	20.00	20.00
1	FRT BUMPER TOWING COVER (WCP)	SERVICEABLE	8.00	-
1	FRT BUMPER FOG LAMP GARNISH RH (WCP)	CRACKED	20.00	20.00
1	FRT BUMPER SIGNAL LAMP RH (WCP)	MISSING / BROKEN	95.00	95.00
1	FRT BUMPER INNER SPONGE (WCP)	TORN	70.00	70.00
1	FRT BUMPER REINFORCEMENT (WCP)	NOT NECESSARY	235.00	-
1	FRT BUMPER BEAM RH (BELOW HEADLAMP) (WCP)	CRACKED	22.00	22.00
1	RH HEADLAMP (WCP)	CRACKED	500.00	500.00
1	HEADLAMP SUPPORT PANEL (WCP)	SERVICEABLE	300.00	-
1	WASHER TANK (WCP)	DEFORMED	40.00	40.00
1	FRT RH FENDER INNER COWLING (WCP)	TORN	45.00	45.00
10	INNER COWLING CLIP (WCP)	NECESSARY	20.00	20.00
1	FRT BUMPER LOWER TRIM RH (WCP) (ADDITIONAL)	TORN	75.00	75.00
1	FRT BUMPER INNER GARNISH RH (WCP) (ADDITIONAL)	TORN	10.00	10.00
1	FRT BUMPER SIDE DEFLECTOR RH (WCP) (ADDITIONAL)	MISSING	20.00	20.00
	COST PLUS 10%		275.00	219.90
			3,025.00	2,418.90
	<b><u>LABOUR</u></b>			
	WIRE CHECKING.		30.00	20.00
	REMOVE & REFIX AIRCON AND GAS.	NOT NECESSARY	100.00	-
	REPAIR FRT RH SPORTS RIM.		100.00	80.00
	WHEEL ALIGNMENT.		65.00	60.00
	LABOUR CHARGE.		700.00	450.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		700.00	360.00
			1,695.00	970.00
GRAND TOTAL			4,720.00	3,388.90
RECOMMENDED COST OF REPAIRS				3,388.90
LESS EXCESS				-750.00
NETT LIABILITY				2,638.90

Report Ref No. CS/SMO20014427/Uvd3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.