

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014434/KTD3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00169792000
Claimant Vehicle No :	SKX2724A	Insured Vehicle No :	SLD2093E
Date of Loss:	21/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D204988/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX2724A		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2211827A
Reg. Date:	03/12/2015 (Man. Year: 2015)	Chassis No:	SJNFEAJ11U1534250
Colour:	Metallic Pearl White	Odometer:	107000 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Yokohama 3 mm	Rear Left Side:	Yokohama 2 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	Yokohama 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,727.39	1,115.75	1,611.64	59.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,235.00	410.00	825.00	66.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,962.39	1,525.75	2,436.64	61.49

INSPECTION

Date of Assignment:	24/12/2020	
Date Inspected:	28/12/2020 Inspected At:	Massive Trading & Auto Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2 Singapore 569541
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX2724A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR END PANEL	Repair	482.60 FL	*- FL
2	1		*REAR END PANEL INNER GARNISH	Serviceable	155.10 FL	*- FL
3	1		*REAR BUMPER	Buckled	796.70 FL	*796.70 FL
4	1		*REAR BUMPER REINFORCEMENT	Repair	691.50 FL	*- FL
5	1		*REAR BUMPER TOW COVER	Dented	55.10 FL	*55.10 FL
6	2		*REAR BUMPER RETAINER	Serviceable	170.20 FL	*- FL
7	2		*REAR BUMPER REFLECTOR	Serviceable	180.20 FL	*- FL
8	1		*REAR BUMPER SPONGE	Cracked	165.70 FL	*165.70 FL
9	1		*SET REAR BUMPER SENSOR (4 PCS)	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,997.10	1,217.50
- List Item Discount on L Items 10.00/10.00% (\$)	269.71	101.75
Total Parts (\$)	2,727.39	1,115.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE /RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	600.00	200.00
2	TO PUTTY & SPRAY PAINT REAR ACCIDENT AFFECTED PORTION	New	600.00	200.00
3	CHECK AND RECONNECT WIRING	New	35.00	10.00
Gross Labour Cost (S\$)			1,235.00	410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >