

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014439/UVD3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00039082001	
Claimant Vehicle No :	SLR7909X	Insured Vehicle No :	GW8180G	
Date of Loss:	22/12/2020	Nature of Claim:	TP	Claim No: SNM20D204990/C02/GW8180G/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR7909X		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	L15B4421507
Reg. Date:	29/08/2017 (Man. Year: 2017)	Chassis No:	RU11221503
Colour:	Purple	Odometer:	49605 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	885.68	836.64	49.04	5.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	710.00	270.00	440.00	61.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,595.68	1,106.64	489.04	30.65
Approved Total (Overridden) (S\$)		850.00		
(S\$)	1,595.68	850.00	745.68	46.73
+ GST 7.00/7.00% (S\$)	111.70	59.50	52.20	46.73
Nett Amount (S\$)	1,707.38	909.50	797.88	46.73

INSPECTION

Date of Assignment:	08/01/2021		
Date Inspected:	30/12/2020	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jan 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR7909X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Grazed	532.10 FL	*532.10 FL
2	1		*O/S REAR BUMPER PAD	Cut	195.00 FL	*195.00 FL
3	1		*O/S REAR WHEEL ARCH GARNISH	Grazed	195.00 FL	*173.20 FL
4	1		*SET REAR MUDFLAP	Grazed	185.00 FL	*145.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,107.10	1,045.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	221.42	209.16
Total Parts (\$\$)	885.68	836.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME }	New	250.00	120.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR }	New	80.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	380.00	150.00
Gross Labour Cost (\$\$)			710.00	270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >