

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014445/R1VD3Q2

Date: 18/02/2021

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00163402000

Claimant  
Vehicle No : SKE8111DInsured  
Vehicle No : SMM8786R

Date of Loss: 21/12/2020

Nature of  
Claim: TPClaim  
No: SNM20D204991/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE8111D**

Make &amp; Model: BMW 420I, 2.0 Gran Coupe (A)

Engine No: F2023000B48B20A

Reg. Date: 31/05/2018 (Man. Year: 2018)

Chassis No: WBA4H320X0BP26779

Colour: Black

Odometer: 25655 km

Engine Capacity: 1998 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45R18

Rear Tyre Size: 225/45R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,243.30	1,523.90	719.40	32.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,733.30</b>	<b>3,457.90</b>	<b>1,275.40</b>	<b>26.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>331.33</b>	<b>242.05</b>	<b>89.28</b>	<b>26.95</b>
<b>Nett Amount (S\$)</b>	<b>5,064.63</b>	<b>3,699.95</b>	<b>1,364.68</b>	<b>26.95</b>

### INSPECTION

Date of Assignment: 26/01/2021

Date Inspected: 25/01/2021 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 17 Feb 2021)	
<b>Parts:</b>	N/A	BMW 420I 2.0 Gran Coupe (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKE8111D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER CARRIER ECE	Serviceable	470.25 FS	*- FS
2	1		*RR BUMPER RH SIDE GUIDE	Serviceable	55.75 FS	*- FS
3	1		*REAR BUMPER CENTRE GUIDE	Serviceable	55.75 FS	*- FS
4	1		*REAR BUMPER BOTTOM REINFORCEMENT	Serviceable	73.75 FS	*- FS
5	1		*TRIM STRIP (SPORT LINE)	Scratched	99.15 FS	*99.15 FS
6	1		*REAR BUMPER PANEL PRIMED (LINE/PDC)	Deformed	1,281.30 FS	*1,281.30 FS
7	1		*FLAP TOWING EYE PRIMED	Serviceable	43.50 FS	*- FS
8	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.40 FS	*- FS
9	1		*COVER	Cracked	63.45 FS	*63.45 FS
10	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
					<b>Total Parts (S\$)</b>	<b>2,243.30      1,523.90</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER PANEL	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>2,490.00</b>	<b>1,934.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >