LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20014447/GTD3E2

Date: 04/05/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant Vehicle FY5192T Insured Vehicle No: SHB4062P

No:

Date of Loss: 23/12/2020 Nature of Claim: TP Claim No: MCT20120473

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FY5192T

 Make & Model:
 HONDA ANF125, 125cc (A)
 Engine No:
 JC33E5021381

 Reg. Date:
 12/10/2004 (Man. Year: 2003)
 Chassis No:
 MLHJC33A135021381

Colour: Black Odometer: 5050 km

Engine Capacity: 125 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 80/90-17 Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,293.00	678.90	2,614.10	79.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	770.00	200.00	570.00	74.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	4,063.00	878.90	3,184.10	78.37
Approved Total (Overridden) (S\$	5)	700.00		
(53	4,063.00	700.00	3,363.00	82.77
+ GST 7.00/7.00% (S\$	284.41	49.00	235.41	82.77
Nett Amount (S	4,347.41	749.00	3,598.41	82.77

INSPECTION

Date of Assignment: 24/12/2020

Ss Motoring (HQ)

Date Inspected: 24/12/2020 Inspected At: 1084 SERANGOON ROAD

Singapore 328186

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 May 2021)

Parts: N/A HONDA ANF125 125cc (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FY5192T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FORK INNER TUBES	Not Necessary	240.00 FL	*- FL
2	2		*FORK OUTER TUBES	Not Necessary	250.00 FL	*- FL
3	1		*FORK UNDER BRACKET	Not Necessary	185.00 FL	*- FL
4	1		*FRONT RIM SHAFT	Not Necessary	42.00 FL	*- FL
5	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*- FL
6	1		*FRONT BRAKE DISC	Not Necessary	155.00 FL	*- FL
7	1		*HEADLAMP	Cut	95.00 FL	*95.00 FL
8	1		*O/S SIDE MIRROR	Cut	48.00 FL	*48.00 FL
9	1		*FRONT SIGNALS (2PCS)	Cut (1Pc Only)	100.00 FL	*45.00 FL
10	1		*HANDLE-BAR	Not Necessary	8.00 FL	*-FL
11	2		*HANDLE-BAR ENDS	Not Necessary	70.00 FL	*- FL
12	1		*SET HAND GRIP	Not Necessary	50.00 FL	*- FL
13	1		*BRAKE LEVER	Cut	32.00 FL	*32.00 FL
14	1		*FRONT FOOTREST BRACKET	Cut	55.00 FL	*48.00 FL
15	1		*FRONT FOOTREST RUBBERS (2PCS)	Cut (1Pc Only)	56.00 FL	*22.00 FL
16	1		*GEAR PEDAL	Not Necessary	40.00 FL	*-FL
17	1		*BRAKE PEDAL	Cut	42.00 FL	*42.00 FL
18	1		*REAR O/S FOOTREST	Cut	38.00 FL	*38.00 FL
19	1		*REAR O/S FOOTREST BRACKET	Not Necessary	65.00 FL	*- FL
20	1		*EXHAUST ASSY	Not Necessary	425.00 FL	*- FL
21	1		*EXHAUST PROTECTOR	Cut	65.00 FL	*38.00 FL
22	1		*REAR FENDER	Torn	68.00 FL	*68.00 FL
23	1		*MAIN STAND	Not Necessary	75.00 FL	*-FL
24	1		*SIDE STAND	Not Necessary	58.00 FL	*- FL
25	1		*BASKET	Not Necessary	35.00 FL	*- FL
26	1		*SET FAIRING ASSY	Cut	525.00 FL	*95.00 FL
27	1		*SET NUMBER PLATE	Bent	28.00 FS	*15.00 FS
28	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
29	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
30	1		*SET STEERING CONE BEARING	Not Necessary	85.00 FS	*- FS
31	1		*REAR BOX	Cut	250.00 FS	*150.00 FS
32	1		*REAR BOX BRACKET	Not Necessary	100.00 FS	*- FS
33	1		*ERP IU	Not Necessary	170.00 FS	*- FS
		part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	3,579.00	736.00
			- List Item Discount o	on L Items 10.00/10.00% (S\$)	286.00	57.10
				Total Parts (S\$)	3,293.00	678.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO CHECK ELECTRICAL SYSTEM, WIRE HARNESS AND FOCUS HEADLAMP	New	50.00	0.00
3	TO PROVIDE LABOUR CHARGES, WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS; REALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	320.00	200.00
4	TO CHECK, REPAIR AND STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION	New	350.00	0.00
	Gross Labour Cost (S\$)		770.00	200.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >