

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/III20014450/QVD3E2  
**Date:** 04/01/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No:  
**Claimant Vehicle No** SKK1080Z **Insured Vehicle No :** SHD4271S  
Date of Loss: 22/12/2020 Nature of Claim: TP Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKK1080Z**  
Make & Model: JAGUAR XF, 2.2 I4D AUTO ABS D/AB 2WD 4DR HID TC (A) Engine No: 4024205224DT  
Reg. Date: 30/03/2013 (Man. Year: 2013) Chassis No: SAJAC0567DDS81495  
Colour: Red Odometer: 0 km  
Engine Capacity: 2179 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/45Z R18 Rear Tyre Size: 245/45Z R18  
Front Left Side: KAPSEN 6 mm Rear Left Side: KAPSEN 6 mm  
Front Right Side: KAPSEN 6 mm Rear Right Side: KAPSEN 6 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

Date of Assignment: 24/12/2020  
Date Inspected: 24/12/2020 Inspected At: Kee Yong Automobile Service (HQ)  
Singapore 575722  
Estimated Period of Repair: 0.0 days

**Adjuster:** OI SUN PIN

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

# REPAIR DETAILS

|               |  |  |
|---------------|--|--|
| Reference     |  |  |
| Part Source:  | MRM-SG   | Version: 1.0 (Last Synchronised: 04 Jan 2021)  |
| Parts:        | 143  | JAGUAR XF 2.2 I4D AUTO ABS D/AB 2WD 4DR HID TC (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's   | (Price-denominated Standard List)  |
| Print Code:   | (Unsubmitted, no print-code for SKK1080Z)  |  |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

## Recommended Parts

There are no new parts selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >