



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 2269Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT HEADLAMP ASSY	SCRATCHED	3,209.30	3,209.30
1	FRONT FENDER	DENTED	398.40	398.40
1	FRONT FENDER TOP RUBBERSEAL	SERVICEABLE	99.70	-
1	FRONT FENDER INNER SHIELD CLIPS	NECESSARY	40.00	40.00
1	FRONT FENDER INNER SHIELD	CUT	195.60	195.60
1	BUMPER	CRUMPLED	1,280.00	1,151.30
1	BUMPER SIDE RETAINER	BROKEN	39.80	39.80
1	SPORT RIM	SCRATCHED	700.00	700.00
	LESS 20% DISCOUNT		-	-1,146.88
			5,962.80	4,587.52
	<b><u>LABOUR</u></b>			
	TO FOCUS HEADLAMP & COMPUTERISED RESETTING.		150.00	50.00
	TO WHEEL ALIGNMENT.		150.00	60.00
	PANEL BEATING.		800.00	450.00
	SPRAY PAINTING.		800.00	400.00
			1,900.00	960.00
<b>GRAND TOTAL</b>			<b>7,862.80</b>	<b>5,547.52</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,450.00</b>

Report Ref No. CS/FCI20014466/Qvd3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.