



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 6366A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT FENDER RH	BENT	588.80	588.80
1	FRT FENDER BLUE -DRIVE RH	NECESSARY	26.60	26.60
1	FRT DOOR RH	BENT	1,797.20	1,797.20
1	FRT DOOR LWR MOULDING RH	TO REPAIR SEE LABOUR	186.20	-
1	FRT WHEEL CAP RH	CUT	346.40	346.40
	LESS 20% DISCOUNT		-589.04	-551.80
			2,356.16	2,207.20
SPECIAL NETT ITEMS				
1	FRT FENDER ADV.STICKER RH (SN)	CUT	100.00	100.00
1	FRT DOOR ADV .STICKER RH (SN)	CUT	100.00	100.00
			200.00	200.00
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT DOOR LWR MOULDING RH .		500.00	480.00
	SPRAYPAINT CHARGE.		500.00	400.00
	TUFF COAT ON AFFECTED PARTS.		40.00	30.00
	TRANSFER OF DOOR .		120.00	60.00
	WHEEL ALIGNMENT .		120.00	80.00
			1,280.00	1,050.00
GRAND TOTAL			3,836.16	3,457.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,700.00

Report Ref No. NS/INC20014474/T1qd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.