5/20/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20014482/KPA3Q2

Date:

20/05/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

1900262471 SKF1759B

Claimant Vehicle No:

SHB7535Y 22/12/2020 Insured Vehicle No: Nature of Claim:

TP

Claim No:

6789551901SG

JTDKB3FU103077070

2ZR2B77395

236567 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB7535Y

Make & Model: TOYOTA PRIUS, 1.8 (A)

04/12/2018 (Man. Year: 2018) Reg. Date:

Colour: Metallic Pearl White/Red

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

Front Right Side:

195/65 R15 Sailun 8 mm Sailun 8 mm

Rear Tyre Size: Rear Left Side:

195/65 R15 Sailun 8 mm

Rear Right Side:

Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,368.30	1,937.80	2,430.50	55.64
Miscellaneous Items		0.00	0.00	0.00	
Labour		9,990.00	870.00	9,120.00	91.29
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	14,358.30	2,807.80	11,550.50	80.44
	+ GST 7.00/7.00% (S\$)	1,005.08	196.55	808.53	80.44

Nett Amount (S\$)	15,363.38	3,004.35	12,359.03	80.44
+ Loss of I	Jse (3.0 x S\$50.00/day) (S\$)	150.00		
+ Car Rei	ntal (3.0 x S\$96.30/day) (S\$)	288.90		
	+ Doc/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	3,450.70		
(Global Sum Settlement (S\$)	3,450.00		

INSPECTION

Date of Assignment: 23/12/2020

Trans-cab Auto Services Pte Ltd Date Inspected: Inspected At: No 2 Ang Mo Kio Street 63 23/12/2020

Singapore 569111

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No. Qty Part N	o. Particulars	Condition	Repairer's	Amount
1 1	*COVER ,REAR BUMPER	Buckled	442.60 FL	*442.60 FL
2 1	*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3 1	*GUARD ,REAR BUMPER ,CENTER	Buckled / Dented	576.30 FL	*576.30 FL
4 1	*COVER ,REAR BUMPER ,LOWER	Missing	15.40 FL	*15.40 FL
5 1	*RETAINE ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
6 1	*RETAINE ,REAR BUMPER SIDE ,RH	Distorted	117.70 FL	*117.70 FL
7 1	*FILLER ,REAR BUMPER EXTENSION ,RH	Mtg Cracked	123.70 FL	*123.70 FL
8 1	*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	88.50 FL	*- FL
9 1	*LENS & BODY ,REAR COMBINATION LAMP RH	Serviceable	451.80 FL	*- FL
10 1	*LENS AND BODY ,REAR LAMP ,RH	Cracked	502.00 FL	*502.00 FL
11 1	*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
12 1	*COVER ,FLOOR UNDER ,NO ,1 (LH)	Serviceable	175.10 FL	*- FL
13 1	*COVER ,FLOOR UNDER ,NO ,1 (RH)	Serviceable	241.90 FL	*- FL
14 1	*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
15 1	*SET PARKING AID	Dented	700.00 FS	*250.00 FS
16 1	*SET REAR BUMPER CLIP	Necessary	95.00 FS	*60.00 FS
17 1	*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*30.00 FS
18 1	*SET REAR FENDE LINER CLIP	Not Necessary	85.00 FS	*- FS
19 1	*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
20 1	*SET TAILLAMP LOWER CLIP	Not Necessary	55.00 FS	*- FS
21 1	*SET TAILLAMP UPPER CLIP	Necessary	55.00 FS	*15.00 FS
22 1	*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS
F=Franchise part. S=S	pcNett. L=ListItemDisc.			
		Sub Total (S\$)	5,384.40	2,465.40
		- List Item Discount on L Items 25.00/25.00% (S\$)	1,016.10	527.60
		Total Parts (S\$)	4,368.30	1,937.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
_ Lab	our Items			
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,200.00	300.00
3	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
5	TO REMOVE AND REFIT ELECTRICAL WIRING ,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
6	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
7	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
8	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
11	TOWING FEES	New	150.00	0.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	500.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
15	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
17	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
18	TO LIFT -UP /OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
19	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS -MEMBER AND OTHER NECESSARY ITEM TO ENABLE BODYWORK REPAIR	New	380.00	0.00
20	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORES	New	380.00	0.00
	Gross Labo	ur Cost (S\$)	9,990.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >