

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014511/EVD3Q2

Date: 19/02/2021

REFERENCE

Insured/Claimant:	TAN FANG LING	Policy No:	2070150725	
Date of Loss:	23/12/2020	Nature of Claim:	OD	Claim No: 9516620985SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW1658X			
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)		Engine No:	3A92UJS5395
Reg. Date:	05/11/2020 (Man. Year: 2020)		Chassis No:	MMBSTA13AMH001309
Colour:	Silver		Odometer:	1625 km
Engine Capacity:	1193 cc			
Market Value/New Car Price:	S\$66,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,853.09	3,348.77	504.32	13.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,390.00	1,675.00	715.00	29.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,243.09	5,023.77	1,219.32	19.53
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	5,643.09	4,423.77	1,219.32	21.61
+ GST 7.00/7.00% (S\$)	395.02	309.66	85.36	21.61
Nett Amount (S\$)	6,038.11	4,733.43	1,304.68	21.61

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 28/12/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY,RH	Broken	1,697.00 FL	*1,697.00 FL
2	1		*TANK,WINDSHIELD WASHER	Necessary	74.00 FL	*74.00 FL
3	1		*CAP,WASHER TANK FILLER	Missing	7.00 FL	*7.00 FL
4	1		*FACE,FR BUMPER	Broken	703.00 FL	*703.00 FL
5	1		*AIR DAM,SIDE,FR RH	Not Necessary	19.00 FL	*- FL
6	1		*BRACKET,FR BUMPER SIDE,RH	Broken	8.00 FL	*8.00 FL
7	1		*GARNISH,FR BUMPER,RH	Missing	44.00 FL	*44.00 FL
8	1		*GRILLE ASSY,RADIATOR	Not Necessary	597.00 FL	*- FL
9	1		*COVER,FR BUMPER GRILLE	Broken	157.00 FL	*157.00 FL
10	1		*LAMP ASSY,FOG,FR LH	Broken	303.00 FL	*303.00 FL
11	1		*FENDER,FR RH	Dented	428.00 FL	*428.00 FL
12	1		*SHIELD,FR WHEELHOUSE,RH	Torn	98.00 FL	*98.00 FL
13	1		*WHEEL,DISC	Cut	598.00 FL	*598.00 FL
14	1		*EMBLEM ECO	Necessary	17.00 FS	*17.00 FS
15	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
16	10		*CLIPS (Supplementary)	Necessary	40.00 FL	*40.00 FL
17	6		*RIVETS (Supplementary)	Necessary	24.00 FL	*24.00 FL
18	1		*GARNISH,FR BUMPER SIDE (Supplementary)	Broken	120.00 FL	*120.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,984.00	4,338.00
- List Item Discount on L Items 23.00/23.00% (\$)	1,130.91	989.23
Total Parts (\$)	3,853.09	3,348.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,FRT RH FENDER & AFFECTED AREA	New	1,350.00	675.00
2	PAINT WORK ON FRT BUMPER & FRT RH FENDER	New	700.00	700.00
3	PERFORM RUST PREVENTION	New	40.00	0.00
4	TO TRANSFER FRT RH RIM INCLUDING BALANCING	New	30.00	30.00
5	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
6	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			2,390.00	1,675.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >