



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 3892C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	BONNET (SN)	BENT	1,184.60	1,184.60
1	FRT BUMPER TOP MOUNT (SN)	NOT NECESSARY	380.00	-
1	FRT BUMPER LH INSERT (SN)	NOT NECESSARY	25.70	-
1	FRT BUMPER RH INSERT (SN)	NOT NECESSARY	25.70	-
1	IMPACT ABSORBER TOP (SN)	NOT NECESSARY	46.95	-
1	GRILLE MIDDLE BOTTOM (SN)	NOT NECESSARY	125.70	-
1	FRT BUMPER RH INSERT (SN)	NOT NECESSARY	60.45	-
1	FRONT BUMPER TOWING COVER PRIMED (SN)	NOT NECESSARY	39.15	-
1	FRT BUMPER PANEL PRIMED (SN)	TO REPAIR SEE LABOUR	829.65	-
1	LH ROOF MOULDING PRIMED (SN)	NOT NECESSARY	182.10	-
1	RH GRILLE (BASIS)(SN)	CRACKED	91.60	91.60
2	EMBLEM GROMMET (SN)	NOT NECESSARY	1.70	-
2	GAS STRUT HOOD (SN)	NOT NECESSARY	237.40	-
1	RH LOWER PART OF HOOK LOCK (SN)	NOT NECESSARY	88.40	-
2	STOP BUFFER (SN)	NOT NECESSARY	25.30	-
1	RH SUPPORT (SN)	NOT NECESSARY	132.15	-
1	FRT BUMPER LOWER MOUNT (SN)	NOT NECESSARY	134.45	-
1	ADJUSTER (SN)	NOT NECESSARY	6.35	-
1	FRONT ENGINE HOOD SEALING (SN)	NOT NECESSARY	39.05	-
1	PLAQUE 82MM (SN)	NOT NECESSARY	71.60	-
1	RH HEADLIGHT LED TECHNOLOGY (SN)	CRACKED	2,145.20	2,145.20
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NOT NECESSARY	20.40	-
4	PDC SENSOR ALPINWEISS (300)(SN)	NOT NECESSARY	1,480.00	-
1	FRONT EMBOSS NUMBER PLATE (SN)	NOT NECESSARY	83.00	-
			7,606.60	3,501.40
	<u>LABOUR</u>			
	REPLACE FRONT BONNET,FRONT BUMPER INCLUDE REMOVE ATTACHMENT ETC AND CARRYOUT REPAIR ON ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF FRT BUMPER PANEL PRIMED.		2,550.00	2,125.00

Report Ref No. CS/SMO20014517/R1Ktd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PAINTING FRONT BONNET AND FRONT BUMPER,FENDER.		2,898.00	2,898.00
	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLIGHTS.		177.00	150.00
	TO REPLACE RIGHT HEADLIGHT.		481.00	408.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
			6,224.00	5,681.00
GRAND TOTAL			13,830.60	9,182.40
RECOMMENDED COST OF REPAIRS				9,182.40
LESS EXCESS				-500.00
NETT LIABILITY				8,682.40

Report Ref No. CS/SMO20014517/R1Ktd3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.