



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 197E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRT PANEL OUTER (WCP)	DENTED / BUCKLED	620.00	620.00
1	FRT PANEL "ISUZU" PLATE (WCP)	NECESSARY	130.00	130.00
1	FRT GRILLE (WCP)	CRACKED	360.00	360.00
6	GRILLE CLIPS @\$8.00 (WCP)	NECESSARY	48.00	48.00
1	FRT BUMPER (WCP)	DISTORTED	450.00	450.00
1	FRT BUMPER BRACKET LH (WCP)	BENT	120.00	120.00
1	FRT BUMPER FOG LAMP LH (WCP)	CRACKED	225.00	225.00
1	LH HEADLAMP (WCP)	BROKEN	280.00	280.00
1	LH SIGNAL LAMP (WCP)	BROKEN	110.00	110.00
1	FRT LH CORNER PANEL (WCP)	CRACKED	230.00	230.00
1	LH SIDE MIRROR (WCP)	CUT	75.00	75.00
1	LH SIDE MIRROR BRACKET (WCP)	TO REPAIR SEE LABOUR	245.00	-
1	LH SIDE MIRROR BASE COVER (WCP)	SCRATCHED	50.00	50.00
1	LH HEADLAMP LOWER RUBBER (WCP)	TORN	35.00	35.00
1	LH DOOR (WCP)	DENTED	850.00	850.00
1	LH DOOR SIGNAL LAMP (WCP)	SCRATCHED	85.00	85.00
1	LH DOOR HINGE (LOWER) (WCP)	NOT NECESSARY	90.00	-
1	LH DOOR PROTECTOR (WCP)	GRAZED	70.00	70.00
1	LH STEP GARNISH (WCP)	GRAZED	125.00	125.00
1	LH DOOR PILLAR (FRT) (WCP)	TO REPAIR SEE LABOUR	300.00	-
1	SET FRT WINDSCREEN MOULDING (WCP)	NECESSARY	220.00	220.00
1	LH AIRCON CONDENSER (WCP)	PUNCTURE	600.00	600.00
1	LH AIRCON FAN ASSY (WCP)	CRACKED	480.00	480.00
2	LH AIRCON CONDENSER BRACKET @\$95.00 (WCP)	NOT NECESSARY	190.00	-
1	FRT PANEL "REWARD" STICKER (ADDITIONAL) (WCP)	NECESSARY	40.00	40.00
	COST PLUS 15%		904.20	780.45
			<b>6,932.20</b>	<b>5,983.45</b>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRT WINDSCREEN GUM (SN)	NECESSARY	60.00	40.00
1	FRT LH TYRE (SN)	SERVICEABLE	200.00	-
1	LH DOOR COMPANY STICKER (SN)	NECESSARY	200.00	120.00
			460.00	160.00
<b><u>LABOUR</u></b>				
	WIRE CHECKING.		30.00	20.00
	REMOVE & REFIX FRT WINDSCREEN.		120.00	120.00
	REMOVE & REFIX DASHBOARD.		250.00	200.00
	WHEEL ALIGNMENT.		65.00	60.00
	TOWING FEE.		100.00	100.00
	REMOVE & REFIX AIRCON AND GAS.		100.00	100.00
	REMOVE & REFIX CUSHION AND SEATS.	NOT NECESSARY	180.00	-
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF LH SIDE MIRROR BRACKET AND LH DOOR PILLAR (FRT).		900.00	700.00
	SPRAY PAINTING.		1,000.00	800.00
	LABOUR CHARGE FOR FIREWALL AND FLOOR PANEL (ADDITIONAL).		400.00	300.00
	SPRAY PAINT FOR FIREWALL AND FLOOR PANEL (ADDITIONAL).		400.00	300.00
			3,545.00	2,700.00
<b>GRAND TOTAL</b>			<b>10,937.20</b>	<b>8,843.45</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>8,843.45</b>

Report Ref No. CS/SMO20014525/Uqd3q2

**CHUA KANG SENG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.