

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG20014526/AQD3Q2

**Date:** 27/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SJN276D **Insured Vehicle No :** SKW4848T

Date of Loss: 23/12/2020 Nature of Claim: TP Claim No: 6140573935SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJN276D</b>		
Make & Model:	HONDA FIT, 1.3 G (A)	Engine No:	L13A4134409
Reg. Date:	23/01/2009 (Man. Year: 2008)	Chassis No:	GE61122254
Colour:	Yellow	Odometer:	196114 km
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/60R15	Rear Tyre Size:	195/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,152.32	3,447.84	2,704.48	43.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,620.00	960.00	26.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,732.32</b>	<b>6,067.84</b>	<b>3,664.48</b>	<b>37.65</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,850.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,732.32</b>	<b>4,850.00</b>	<b>4,882.32</b>	<b>50.17</b>

### INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 28/12/2020 Inspected At:

Automobile Hub Enterprise  
1 KAKI BUKIT AVENUE 5, #2 -11  
AUTOBAY @ KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 8.0 days

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	494.60 FL	*494.60 FL
2	2		*REAR BUMPER SIDE HOLDER	Necessary	48.00 FL	*48.00 FL
3	1		*REAR BUMPER TOW COVER	Not Necessary	28.00 FL	*- FL
4	1		*REAR END PANEL	Dented	356.70 FL	*356.70 FL
5	1		*REAR END PANEL TOP GARNISH	Deformed	140.20 FL	*140.20 FL
6	1		*TAILLAMP	N/s Cracked	576.40 FL	*288.20 FL
7	1		*TAILLAMP PANEL	N/s Dented	534.00 FL	*267.00 FL
8	1		*TAILGATE	Distorted	796.00 FL	*796.00 FL
9	1		*TAILGATE LOCK	Damaged	189.50 FL	*189.50 FL
10	1		*TAILGATE WEATHERSTRIPE	Cut	112.40 FL	*112.40 FL
11	1		*TAILGATE OUTER GARNISH	Not Necessary	245.50 FL	*- FL
12	1		*TAILGATE INNER TRIM BOARD	Not Necessary	292.50 FL	*- FL
13	1		*TAILGATE GLASS MOULDING	Necessary	110.00 FL	*110.00 FL
14	1		*HONDA LOGO	Not Necessary	42.50 FL	*- FL
15	1		*FIT EMBLEM	Necessary	45.80 FL	*45.80 FL
16	1		*REAR FENDER INNER TRIM BOARD	N/s Deformed	590.00 FL	*295.00 FL
17	1		*SPARE TYRE PANEL	Repair	837.90 FL	*- FL
18	1		*SPARE TYRE PANEL TOP COVER	Deformed	287.30 FL	*287.30 FL
19	1		*TOOLS TRAY SPONGE	Cracked	279.10 FL	*279.10 FL
20	1		*REAR EXHAUST PIPE	Not Necessary	586.50 FL	*- FL
21	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	35.00 FL	*- FL
22	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
23	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
24	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
25	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
26	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
27	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
28	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
29	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*TAILGATE SURROUND MOULDING	Cut	150.00 FS	*80.00 FS
31	1		*SET TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
32	2		*SET REAR FENDER INNER TRIM BOARD CLIPS	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (S\$)**    **7,477.90**    **4,189.80**  
**- List Item Discount on L Items 20.00/20.00% (S\$)**    1,325.58    741.96

**Total Parts (S\$)**    **6,152.32**    **3,447.84**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING,REMOVE AND REFIT PARTS	New	1,400.00	1,100.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	1,200.00
3	WIRING CHECK	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO APPLY TUFF COAT	New	150.00	60.00
6	TO REMOVE UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	60.00
7	TO REMOVE EXHAUST PIPE	New	150.00	0.00
8	TO REMOVE AND REFIT TAILGATE GLASS	New	180.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>3,580.00</b>	<b>2,620.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**