

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20014528/KTD3E2

Date: 29/03/2021

REFERENCE

Insured/Claimant: ZAP PILING PTE LTD Policy No: DMCVSNW00060852000

Date of Loss: 19/12/2020 Nature of Claim: OD Claim No: SNM20D205061/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF2484T**
Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A) Engine No: ZD30013007N
Reg. Date: 16/08/2016 (Man. Year: 2016) Chassis No: JN1SC2F24Z0858859
Colour: Silver Odometer: 131685 km
Engine Capacity: 2953 cc
Market Value/New Car Price: S\$40,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/80 R15 Rear Tyre Size: 155 R15X8 (D)
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 4/4 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,065.00	3,352.00	713.00	17.54
Miscellaneous Items	78.00	78.00	0.00	0.00
Labour	2,260.65	2,218.65	42.00	1.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,403.65	5,648.65	755.00	11.79
Approved Total (Overridden) (S\$)		4,500.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	6,403.65	4,000.00	2,403.65	37.54
+ GST 7.00/7.00% (S\$)	448.26	280.00	168.26	37.54
Nett Amount (S\$)	6,851.91	4,280.00	2,571.91	37.54

INSPECTION

Date of Assignment: 28/12/2020 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 28/12/2020 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761
Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Mar 2021)

Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF2484T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		4,065.00 F	*3,352.00 F
					Total Parts (\$)	3,352.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	78.00	78.00
			Sub Total (\$)	78.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	1,386.00	1,344.00
2	SPRAY PAINTING	New	874.65	874.65
			Gross Labour Cost (\$)	2,260.65

Report was unsubmitted during this print-out.

< END OF ESTIMATES >