

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014529/ETD3E2

Date: 22/01/2021

REFERENCE

Insured/Claimant:	LIM SI JIE	Policy No:	2070009194		
Date of Loss:	25/12/2020	Nature of Claim:	OD	Claim No:	7949744551SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR8654L		
Make & Model:	KIA STONIC, 998cc (A)	Engine No:	G3LCKP080193
Reg. Date:	29/01/2020 (Man. Year: 2019)	Chassis No:	KNAD6811VL6326726
Colour:	Blue	Odometer:	4441 km
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,365.00	2,641.20	2,723.80	50.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	3,250.00	400.00	10.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,015.00	5,891.20	3,123.80	34.65
+ GST 7.00/7.00% (S\$)	631.05	412.38	218.67	34.65
Nett Amount (S\$)	9,646.05	6,303.58	3,342.47	34.65

INSPECTION

Date of Assignment:	28/12/2020		
Date Inspected:	28/12/2020	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FRT NUMBER PLATE WITH FRAME	Necessary	50.00 FS	*50.00 FS
3	1		*COVER-FR BUMPER, LWR	Cut	367.00 F	*367.00 FL
4	1		*COVER-FR BUMPER UPR	Repair	476.00 F	*- FL
5	1		*BRACKET- FR BUMPER SIDE, RH	Broken	13.00 F	*13.00 FL
6	1		*PANEL-FENDER, RH	Dented	401.00 F	*401.00 FL
7	1		*INSULATOR-FENDER RH	Crushed	27.00 F	*27.00 FL
8	1		*GUARD ASSY-FRONT WHEEL, RH	Crushed	56.00 F	*56.00 FL
9	1		*PANEL ASSY-FRONT DOOR, RH	Dented	858.00 F	*858.00 FL
10	1		*TAPE-FR DR BLACK FRAME RR,RH	Necessary	13.00 F	*13.00 FL
11	1		*BLACK TAPE-FR DR FRAME UPR, RH	Necessary	13.00 F	*13.00 FL
12	1		*MOULDING ASSY-SIDE SILL, RH	Not Necessary	248.00 F	*- FL
13	1		*WHEEL ASSY-ALUMINIUM	Cut	790.00 F	*790.00 FL
14	1		*HUB ASSY-FR WHEEL	Necessary	145.00 F	*145.00 FL
15	1		*BEARING-FRONT WHEEL HUB	Jammed	131.00 F	*131.00 FL
16	1		*KNUCKLE-FRONT AXLE, RH	Not Necessary	340.00 F	*- FL
17	1		*LINK-STABILIZER	Not Necessary	94.00 F	*- FL
18	1		*GEAR ASSY-STEERING	Not Necessary	923.00 F	*- FL
19	1		*STRUT ASSY-FR, RH	Bent	269.00 F	*269.00 FL
20	1		*GARNISH ASSY - FNDR SIDE, RH (Supplementary)	Crushed	45.00 F	*45.00 FL
21	1		*GARNISH ASSY - FR DR SIDE, RH (Supplementary)	Cut	82.00 F	*82.00 FL
22	2		*NUT - PLUG (Supplementary)	Necessary	4.00 F	*4.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,365.00	3,284.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	642.80
Total Parts (S\$)	5,365.00	2,641.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT FENDER RH, FRT DOOR RH	New	1,600.00	1,200.00
2	REMOVE & INSTALL FRT DOOR TRIMS AND GLASS	New	180.00	180.00
3	SPRAY PAINTN FOR FRT BUMPER, FRT FENDER RH, FRT DOOR RH	New	1,050.00	1,050.00
4	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
5	TRANSFER FRT RIM	New	30.00	30.00
6	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
8	RENEW FRT UNDERCARRIAGE	New	400.00	400.00
9	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
10	APPLY RESEAL FRT NUMBER PLATE FROM LTA	New	80.00	80.00
Gross Labour Cost (S\$)			3,650.00	3,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >