

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20014534/UBA3Q2
Date: 27/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100004797
Claimant
Vehicle No : SDW9078Z **Insured Vehicle No :** SCG50H
 Date of Loss: 26/12/2020 Nature of Claim: TP Claim No: 6737880871SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDW9078Z**
 Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B14101722
 Reg. Date: 09/09/2019 (Man. Year: 2019) Chassis No: JHMGK3850KS218164
 Colour: Blue Odometer: 26624 km
 Engine Capacity: 1318 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,314.72	1,158.32	1,156.40	49.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,370.00	990.00	1,380.00	58.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,684.72	2,148.32	2,536.40	54.14
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	4,684.72	1,700.00	2,984.72	63.71
+ GST 7.00/7.00% (S\$)	327.93	119.00	208.93	63.71
Nett Amount (S\$)	5,012.65	1,819.00	3,193.65	63.71
+ Car Rental (2.5 x S\$100.00/day + 7.00% GST) (S\$)		267.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,088.50		

INSPECTION

Date of Assignment: 28/12/2020
 Date Inspected: 28/12/2020 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 1 Defu Lane 6
 Singapore 539365
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S FRONT FENDER	Badly Dented	481.40 FL	*481.40 FL
2	1		*N/S FRONT FENDER INNER COWLING	Deformed / Twisted	67.20 FL	*67.20 FL
3	6		*N/S FRONT FENDER INNER COWLING CLIPS	Necessary	27.00 FL	*27.00 FL
4	1		*N/S FRONT DOOR	Badly Dented	872.30 FL	*872.30 FL
5	1		*N/S FRONT DOOR POWER WINDOW MOTOR	Not Necessary	390.60 FL	*- FL
6	1		*N/S FRONT DOOR REGULATOR	Not Necessary	238.70 FL	*- FL
7	1		*N/S FRONT DOOR TOP HINGE	Not Necessary	45.80 FL	*- FL
8	1		*N/S FRONT DOOR BOTTOM HINGE	Not Necessary	45.80 FL	*- FL
9	1		*N/S FRONT DOOR MIRROR ASSY	Not Necessary	637.80 FL	*- FL
10	1		*N/S FRONT FENDER 1/4 GLASS INNER SEAL	Not Necessary	36.80 FL	*- FL
11	1		*N/S FRONT FENDER 1/4 GLASS SEALANT	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,883.40	1,447.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	568.68	289.58
Total Parts (\$\$)	2,314.72	1,158.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT N/S FRONT FENDER 1/4 GLASS	New	120.00	0.00
2	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	120.00	60.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	300.00	60.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	900.00	300.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	550.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (\$)			2,370.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >