

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20014543/GVD3E2  
**Date:** 05/01/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100417522		
<b>Claimant Vehicle No :</b>	SMS8459D	<b>Insured Vehicle No :</b>	SKT7561R		
Date of Loss:	22/12/2020	Nature of Claim:	TP	Claim No:	2182006214SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS8459D	Engine No:	L15B6024047
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK82103487
Reg. Date:	18/03/2020 (Man. Year: 2019)	Odometer:	24822 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/50ZR16	Rear Tyre Size:	205/50ZR16
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	28/12/2020		
Date Inspected:	28/12/2020	Inspected At:	1st Auto Pro Pte Ltd - 8 Kaki Bukit (HQ) 8 Kaki Bukit Avenue 4, #01-51/52 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER TOW COVER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
5	1		*REAR BUMPER REFLECTOR	Cracked	0.00 F	*- F
6	1		*REAR END PANEL	Buckled	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
8	1		*TAILGATE	Buckled	0.00 F	*- F
9	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
11	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
12	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
13	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
14	1		*SPARE TYRE BOARD	Cut	0.00 F	*- F
15	1		*SPARE TYRE TOOL BOX	Cracked	0.00 F	*- F
				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >