



Your Ref : SNM20D204841/C01/LEWLC

Date: 31st March 2021

Our Ref : CS/CTI20014547/Ktd3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMT 3314R
ACCIDENT ON 09/12/2020**

Instruction was received to inspect the vehicle Reg. No. SMT 3314R. The inspection was conducted on 29/12/2020 at the premises of M/s 10 Ang Mo Kio Ind Park 2A #01-04, Repairer: Cheng Hoe Motor Pte Ltd.

The following vehicle information was recorded:

Registration Number	: SMT 3314R
Make/Model	: Toyota Vios E Manual
Year of Registration	: 2008
Body Colour	: White
Chassis Number	: MR053HY9305079525
Engine Capacity	: 1497 cc

The vehicle sustained damages at the front portion and o/s rear body. The undercarriage and body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 17,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 9,084.00)
Nett Liability	<u>S\$ 7,916.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.