

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 30 Dec 2020

Preliminary Advice

Insured Vehicle No	: SLJ5115A	Accident Date	: 26/12/2020
TP Vehicle No	: SGP9285T	Assignment Date	: 28/12/2020
Make	: TOYOTA VIOS	Est. Duration of Repair	: 6
Date of Inspection	: 28/12/2020		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,067.53
Revised Amount	:S\$	3,792.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,792.60
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	6,800.00
COE / PARF Rebate	:S\$	5,127.00
Salvage Value	:S\$	
Margin for Repair	:S\$	1,673.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 () Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 THE REPAIRER ASKING REPAIR COST AT LUMP SUM \$3,000.00.