

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2100891

3 ANSON ROAD #16-00 INV Date 09/02/2021 SPRINGLEAF TOWER Reference CC3/CTI20014554/T1ea3q2

SINGAPORE 079909 Code CTI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 1156L

Insured Veh. SLQ 9375C

Claim No. SNM20D205150

Policy No.

Accident Date 22/12/2020

Inspection Date 22/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Ref:	CC3/CTI20014554/T1ea3q2		
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Date:	09/02/2021		
			Code:	CTI		
1.		Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLQ 9375C	Veh. Inspected	SHD 1156L		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	SNM20D205150	Excess (\$)	0.00		
	Assign From		Assign Date	22/12/2020		
2.		Vehicle Partic	culars & Condition			
	Make & Model	KIA OPTIMA	c.c	1685		
	Engine No.	HIDDEN	Year of Reg.	2015		
	Chassis No.	KNAGM414MF5578134	Colour	SILVER		
	Odometer	671831 KM	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	205/65 R15	HANKOOK	6 mm		
	L/H Front Tyre	205/65 R15	HANKOOK	6 mm		
	R/H Rear Tyre	205/65 R15	HANKOOK	6 mm		
	L/H Rear Tyre	205/65 R15	HANKOOK	6 mm		
4.		•	on of Damages			
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRO	ONT N/S PORTION.			
	DAMAGES SEE DI	ETAILS.				
5.		General	Information			
	Accident Date	22/12/2020	Inspection Date	22/12/2020		
	Survey held at	PREMIER AUTOMOTIVE SERVI	ICES PTE LTD			
		23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443				
5a.			emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	2 Work	ing Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1156L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT N/S HEAD LAMP	NOT NECESSARY	1,028.00	-
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER EMBLEM	NOT NECESSARY	44.00	-
2	FRONT BUMPER N/S & O/S SIDE RETAINER @\$16.00	N/S NECESSARY / O/S NOT NECESSARY	32.00	16.00
1	FRONT BUMPER N/S PROTECTOR	NOT NECESSARY	51.00	-
1	FRONT N/S FOG LIGHT COVER	NOT NECESSARY	66.00	-
1	FRONT N/S WHEEL COVER	NOT NECESSARY	116.00	-
1	FRONT N/S FENDER	BENT	384.00	384.00
1	FRONT N/S FENDER INNER SHIELD	DEFORMED	120.00	120.00
	LESS 10% DISCOUNT		-237.20	-105.10
			2,134.80	945.90
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	30.00
1	FRONT N/S FENDER STICKER (SN)	NECESSARY	30.00	30.00
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			156.00	88.00
	<u>LABOUR</u>			
	TO FOCUS AND ADJUST FRONT N/S & O/S HEAD LAMPS.	NOT NECESSARY	60.00	-
	TO CHECK FRONT N/S WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SAME,ETC.		650.00	200.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER,FRONT N/S FENDER.		400.00	400.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	30.00
			1,310.00	630.00
	GRAND TOTAL		3,600.80	1,663.90

Report Ref No. CC3/CTI20014554/T1ea3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC3/CTI20014554/T1ea3q2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

Automotive Assessor

Amonto

**HO LEONG CHUAN** 

**Automotive Assessor** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 1156L

#### **INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SHD 1156L

#### **RE-INSPECTION**









