

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20014555/T1QD3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MF000013

Claimant

Vehicle No : SHC8395Y

Insured Vehicle No : FBH7914B

Date of Loss: 26/12/2020

Nature of Claim: TP

Claim No: M2006408

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC8395Y**

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4DFDU538550

Reg. Date: 20/08/2015 (Man. Year: 2015)

Chassis No: KMHLB41UMGU077122

Colour: Blue

Odometer: 0 km

Engine Capacity: 1685 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

Good

CONDITION OF TYRES

Front Tyre Size: 205/60R16

Rear Tyre Size:

205/60R16

Front Left Side: West Lake 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,221.96	2,184.36	37.60	1.69
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	600.00	480.00	120.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,832.96	2,675.36	157.60	5.56
Approved Total (Overridden) (S\$)		2,150.00		
(S\$)	2,832.96	2,150.00	682.96	24.11
+ GST 7.00/7.00% (S\$)	198.31	150.50	47.81	24.11
Nett Amount (S\$)	3,031.27	2,300.50	730.77	24.11

INSPECTION

Date of Assignment: 28/12/2020 Present Location:

ComfortDelGro Engineering Pte Ltd
(Loyang)

Date Inspected: 28/12/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8395Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER	Deformed	1,052.20 FL	-	*1,052.20 FL
2	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	-	*1,480.00 FL
3	1		*RADIATOR GRILLE EMBLEM-H	Necessary	129.50 FL	-	*129.50 FL
4	1		*FRT BUMPER UPR BRKT LH	Not Necessary	22.40 FL	-	*- FL
5	1		*FRT BUMPER SIDE BRKT LH	Not Necessary	24.60 FL	-	*- FL
6	1		*FRT NO.PLATE WITH TRIM COVER	Cracked	55.00 F	-	*55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,763.70	2,716.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	541.74	532.34

Total Parts (\$\$)	2,221.96	2,184.36
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	280.00
2	SPRAY PAINTING	New	250.00	200.00
Gross Labour Cost (\$\$)			600.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >