

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20014557/R1PA3Q2

Date: 10/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800143247
Claimant Vehicle No :	SGD666A	Insured Vehicle No :	SMG542L
Date of Loss:	24/12/2020	Nature of Claim:	TP
		Claim No:	8076264515SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGD666A		
Make & Model:	VOLKSWAGEN CC TSI, 1.8 (A)	Engine No:	CDA286377
Reg. Date:	13/04/2012 (Man. Year: 2012)	Chassis No:	WVWZZZ3CZCE702647
Colour:	Brown	Odometer:	197734 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,231.99	0.00	2,231.99	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,590.00	3,020.00	3,570.00	54.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,821.99	3,020.00	5,801.99	65.77
+ GST 7.00/7.00% (S\$)	617.54	211.40	406.14	65.77
Nett Amount (S\$)	9,439.53	3,231.40	6,208.13	65.77
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	29/12/2020	
Date Inspected:	29/12/2020	Inspected At: Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934
Estimated Period of Repair:	4.0 days	

Adjuster: CHEW HSIAO TONG

Manager: MOHD RASUL

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER PRIMED REAR BUMPER	Repair	1,717.30 FS	*- FS
2	1		*DECORATIVE MOULDING BRIGH REAR BUMPER CHROME RH	Serviceable	164.25 FS	*- FS
3	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Serviceable	49.47 FS	*- FS
4	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Serviceable	49.47 FS	*- FS
5	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Serviceable	25.78 FS	*- FS
6	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Serviceable	25.78 FS	*- FS
7	2		*SENSOR BRACKET	Serviceable	32.30 FS	*- FS
8	1		*SENSOR BRACKET	Serviceable	16.15 FS	*- FS
9	1		*SENSOR BRACKET	Serviceable	16.15 FS	*- FS
10	1		*2K-PLASTIC ADHESIVE	Serviceable	75.94 FS	*- FS
11	1		*BONDING AGENT FOR PLASTIC	Serviceable	59.40 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,231.99	0.00
---------------------------	-----------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	WHEEL ALIGNMENT	New	360.00	360.00
4	R&R RIM & BALANCE	New	50.00	0.00
5	LABOUR	New	2,520.00	840.00
6	SPRAY PAINT	New	2,400.00	840.00
7	SPRAY RIM	New	500.00	500.00
Gross Labour Cost (S\$)			6,590.00	3,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >