#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG20014578/R1QD3E2

Date:

05/01/2021

Claim No:

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100468256

**Claimant Vehicle No** 

XE2625Z

Insured Vehicle No:

SFS5212B

Date of Loss:

16/12/2020

Nature of Claim:

ΤP

1378252235SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

Make & Model: Reg. Date:

MITSUBISHI FUSO, 12.0 D FP51SDR3VDEA (M)

Engine No: Chassis No: Odometer:

OM457329461 FP51SDA20131

264178 km

Colour:

Multi-colour

**Engine Capacity:** Market Value/New Car Price: 11967 cc

Sum Insured (S\$):

N/A Market Value/New Car Price

16/02/2017 (Man. Year: 2016)

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable): Yes

Handbrake (Serviceable):

**Engine Modification:** Yes

Pre-accident Condition: Nο

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

Front Right Side:

295/80R22.5 KPATOS 8 mm KPATOS 8 mm Rear Tyre Size: Rear Left Side:

295/80R22.5(D) KPATOS 8/8 mm

Rear Right Side: KPATOS 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment:

28/12/2020

Leng Yong Motor Workshop (HQ)

Date Inspected:

Adjuster:

29/12/2020 Inspected At:

27A Jurong Port Road, #01-28 JTC Industrial Service Centre

Singapore 619101

Estimated Period of Repair:

MOHD RASUL

3.0 days

Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*-F
2	1		*REAR NUMBER PLATE BRACKET	Bent	0.00 F	*- F
3	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F
4	1		*REAR AIR TANK	Repair	0.00 F	*- F
5	1		*REAR CROSS MEMBER	Repair	0.00 F	*- F
F=Fra	anchise	part.				
				Total Parts (S\$)	0.00	0.00
			Report was unsubmitted	during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >