11/17/21, 3:44 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014605/T1GA3Q2

**Date:** 17/11/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100457705

Claimant Vehicle

No: SHC1162Z Insured Vehicle No: SLB995B

Date of Loss: 23/12/2020 Nature of Claim: TP Claim No: 2019985735SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC1162Z

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRS055471

Reg. Date: 29/06/2017 (Man. Year: 2017) Chassis No: JTDKB3FU403561072

Colour: Blue Odometer: 526834 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,394.12	1,211.72	182.40	13.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	720.00	550.00	170.00	23.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,114.12	1,761.72	352.40	16.67
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	2,114.12	1,400.00	714.12	33.78
+ GST 7.00/7.00% (S\$)	147.99	98.00	49.99	33.78
Nett Amount (S\$)	2,262.11	1,498.00	764.11	33.78
+ Loss of Use (2.0 x	S\$50.00/day) (S\$)	100.00		
+ Car Rental (2.0 x S	\$125.40/day) (S\$)	250.80		
+ Do	c/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	1,850.80		
Global Sur	m Settlement (S\$)	1,850.00		

**INSPECTION** 

Date of Assignment: 28/12/2020

Date Inspected: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

#### **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER REAR BUMPER	Deformed	458.60 FL	*458.60 FL
2	10		*BUMPER PIECE	Necessary	22.00 FL	*22.00 FL
3	1		*REINFORCEMENT SUB-ASSY RE	Bent	318.80 FL	*318.80 FL
4	1		*RETAINER RR BUMPER	Not Necessary	94.80 FL	*- FL
5	1		*FILLER -REAR BUMPER EXTENS	Not Necessary	148.40 FL	*- FL
6	1		*REVERSE SENSOR ASSY	Not Working	135.70 FS	*135.70 FS
7	1		*GUARD -REAR BUMPER C	Deformed	552.60 FL	*552.60 FL
8	1		*COVER REAR BUMPER -TOW HOO	Deformed	82.70 FL	*82.70 FL
F=Fra	anchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	1,813.60	1,570.40
			- List Item Discount o	n L Items 25.00/25.00% (S\$)	419.48	358.68
				Total Parts (S\$)	1,394.12	1,211.72
			Report was unsubmitted	during this print-out		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	350.00	320.00
2	SPRAYPAINT ON AFFECTED AREA	New	250.00	200.00
3	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
		Gross Labour Cost (S\$)	720.00	550.00
	Report was	s unsubmitted during this print-out.		

< END OF ESTIMATES >