



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 6427H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DISTORTED	496.40	496.30
1	SET FRONT BUMPER CLIPS	NECESSARY	42.00	42.00
1	FRONT RH SIDE RETAINER	CRACKED	193.10	193.10
1	FRONT RH FOG LAMP GARNISH	TWISTED	68.10	68.10
1	FRONT RH HEADLAMP	SCRATCHED	948.70	848.70
1	FRONT RH STEP PANEL GARNISH	TORN	152.70	152.70
1	FRONT RH DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-475.25	-450.23
			1,425.75	1,350.67
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	ART WORK O/S DOOR (SN)	NECESSARY	280.00	150.00
			280.00	150.00
	<b><u>LABOUR</u></b>			
	SPRAY PAINTING.		680.00	500.00
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF FRONT RH DOOR.		480.00	400.00
	WIRING CHECK.		50.00	20.00
	TUFFCOAT.	NOT NECESSARY	80.00	-
			1,290.00	920.00
	<b>GRAND TOTAL</b>		<b>2,995.75</b>	<b>2,420.67</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,900.00</b>

Report Ref No. CC4/FCI20014610/Ura3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.