



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20014610/Ura3q2	
			Date: 22/02/2021	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 2377U	Veh. Inspected	SLL 6427H	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20005295MFSH/1	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	28/12/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE (A)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFST22P800029808	Colour	SILVER	
Odometer	184469 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MICHELIN	5 mm	
L/H Front Tyre	195 R15	MICHELIN	5 mm	
R/H Rear Tyre	195 R15	MICHELIN	5 mm	
L/H Rear Tyre	195 R15	MICHELIN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/12/2020	Inspection Date	29/12/2020	
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	