

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014612/R1PA3Q2

Date: 29/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800143406

Claimant
Vehicle No : SKS866M **Insured Vehicle No :** GBB1595J

Date of Loss: 26/12/2020 Nature of Claim: TP Claim No: 8830591971SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS866M		
Make & Model:	VOLKSWAGEN SHARAN, 2.0 TSI 7N24MY (A)	Engine No:	DED006917
Reg. Date:	28/11/2016 (Man. Year: 2016)	Chassis No:	WVWZZZ7NZHV211822
Colour:	Grey	Odometer:	31901 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,306.83	16,066.94	5,239.89	24.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,030.00	11,230.00	8,800.00	43.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$)	41,336.83	27,296.94	14,039.89	33.96
+ GST 7.00/7.00% (\$)	2,893.58	1,910.79	982.79	33.96
Nett Amount (\$)	44,230.41	29,207.73	15,022.68	33.96
+ Car Rental (15.0 x S\$120.00/day + 7.00% GST) (\$)		1,926.00		
+ Doc/Search Fee (\$)		2.00		
+ Other Costs (\$)		360.00		
Nett Liability (\$)		31,495.73		

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 29/12/2020 Inspected At:

VOLKSWAGEN GROUP
SINGAPORE PTE LTD
17 TUAS AVENUE
Singapore 639176

Estimated Period of Repair: 13.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED FRT BUMPER	Deformed	1,620.73 FS	*1,539.69 FS
2	1		*BUMPR BRACKET FRT REINFORCEMENT	Bent	764.09 FS	*725.89 FS
3	1		*CAP PRIMED FRT TOWING COVER	Cut	56.24 FS	*53.43 FS
4	1		*GUIDE PIECE FRT BUMPER CTR BRACKET	Cracked	142.12 FS	*135.01 FS
5	1		*GUIDE PIECE FRT BUMPER SIDE BRACKET LH	Cracked	32.35 FS	*30.73 FS
6	1		*GUIDE PIECE FRT BUMPER SIDE BRACKET RH	Cracked	32.35 FS	*30.73 FS
7	1		*GRILL SATIN BLACK FRT BUMPER LOWER GRILLE	Cracked	180.49 FS	*171.47 FS
8	1		*DECORATIVE MOULDING BRIGHT FRT LOWER GRILLE CHROM	Scratched	209.71 FS	*199.22 FS
9	1		*COOLING AIR GRILLE SATIN B RHS FOG LAMP GRILLE	Scratched	173.48 FS	*164.81 FS
10	1		*PROTECTIVE STRIP BRIGHT C RHS FOG LAMP GRILLE CHROM	Serviceable	100.68 FS	*- FS
11	1		*RADIATOR GRILLE SATIN BIA FRT RADIATOR GRILLE	Cracked	644.08 FS	*611.88 FS
12	1		*VW SIGN BLACK HIGH GLASS	Cracked	112.51 FS	*106.88 FS
13	1		*REAR WINDOW GLASS NOT PRE REAR W/SCREEN	Broken	853.67 FS	*810.99 FS
14	1		*1K WINDOW ADHESIVE (2 PCS)	Necessary	99.02 FS	*94.07 FS
15	1		*ALL PURPOSE CLEANER	Necessary	89.22 FS	*84.76 FS
16	1		*PRIMER	Necessary	25.74 FS	*24.45 FS
17	1		*ACTIVATOR FOR PRECOATED W	Necessary	23.77 FS	*22.58 FS
18	2		*APPLICATOR	Necessary	18.78 FS	*17.84 FS
19	1		*REAR TRUNK LID	Bent	2,680.27 FS	*2,546.26 FS
20	1		*DECKLID WEATHERSTRIP	Necessary	317.89 FS	*302.00 FS
21	1		*PACKING ADHESIVE REAR NUMBER PLATE PACKING	Necessary	27.82 FS	*26.43 FS
22	1		*RIVETTED CAP NUT (4 PCS)	Necessary	8.92 FS	*8.47 FS
23	1		*HOOD LATCH BOOT LID LOCK	Serviceable	867.54 FS	*- FS
24	1		*CAP FOR SATIN BLACK LOCK COVER	Serviceable	11.97 FS	*- FS
25	1		*BUTTON FOR ELECTRICALLY PUSH BUTTON	Serviceable	1,236.80 FS	*- FS
26	1		*COVER PUSH BUTTON INNER BRACKET	Serviceable	19.82 FS	*- FS
27	1		*DRIVE UNIT REAR BOOT LID ABSORBER (2 PCS)	Not Working	1,110.98 FS	*1,055.43 FS
28	2		*MOUNTING FOR GAS-FILLED S ABSORBER BRACKET (BODY)	Serviceable	39.28 FS	*- FS
29	1		*MOUNTING FOR GAS-FILLED S LHS ABSORBER BRACKET (LID)	Serviceable	22.10 FS	*- FS
30	1		*MOUNTING FOR GAS-FILLED S RHS ABSORBER BRACKET (LID)	Serviceable	22.10 FS	*- FS
31	1		*VW SIGN BLACK HIGH GLOSS	Necessary	113.71 FS	*108.02 FS
32	1		*INSCRIPTION CHROME NAME PLATE -SHARAN	Necessary	85.53 FS	*81.25 FS
33	1		*INSCRIPTION BRIGHT CHROME NAME PLATE -380 TSI	Necessary	70.04 FS	*66.54 FS
34	1		*ADDITIONAL BRAKE LIGHT WI 3RD BRAKELIGHT	Not Necessary	213.11 FS	*- FS
35	1		*LED TAIL LIGHT WITH BACK-TAILLIGHT INNER LH	Cracked	568.85 FS	*540.41 FS
36	1		*LED TAIL LIGHT WITH BACK-TAILLIGHT INNER RH	Cracked	568.85 FS	*540.41 FS
37	1		*LED TAIL LIGHT TAILLIGHT OUTER LH	Serviceable	623.03 FS	*- FS
38	1		*LED TAIL LIGHT TAILLIGHT OUTER RH	Cracked	623.03 FS	*591.88 FS
39	1		*GROMMET (4 PCS)	Necessary	5.08 FS	*4.83 FS
40	1		*TRIM PANEL FOR HATCH GATE REAR BOOT LID TRIM COVER	Deformed	634.68 FS	*602.95 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR WINDOW FRAME TITANIU RHR BOOT LID TRIM (SIDE)	Serviceable	31.81 FS	*- FS
42	1		*REAR WINDOW FRAME TITANIU LHR BOOT LID TRIM (SIDE)	Serviceable	31.81 FS	*- FS
43	1		*REAR WINDOW FRAME TITANIU REAR BOOT LID TRIM (UPPER)	Cut	73.66 FS	*69.98 FS
44	1		*GROMMET (2 PCS)	Necessary	37.58 FS	*35.70 FS
45	1		*WIPER MOTOR	Serviceable	388.59 FS	*- FS
46	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Deformed	1,250.67 FS	*1,188.14 FS
47	1		*SPOILER SATIN BLACK	Scratched	257.35 FS	*244.48 FS
48	1		*CAP PRIMED REAR BUMPER TOWING COVER	Serviceable	69.55 FS	*- FS
49	1		*BUMPER BRACKET REAR REINFORCEMENT	Bent	755.41 FS	*717.64 FS
50	1		*FOAM INSERT REAR BUMPER FOAM	Cracked	129.26 FS	*122.80 FS
51	1		*EXPANDING NUT (6 PCS)	Necessary	10.50 FS	*9.98 FS
52	1		*ATTACHMENT STRIP REAR BUMPER CTR BRACKET	Cracked	181.89 FS	*172.80 FS
53	1		*GUIDE PIECE REAR BUMPER SIDE BRACKET LH	Serviceable	78.52 FS	*- FS
54	1		*GUIDE PIECE REAR BUMPER SIDE BRACKET RH	Serviceable	78.52 FS	*- FS
55	1		*REAR APRON REAR END PANEL OUTER	Bent	240.16 FS	*228.15 FS
56	1		*ZINC SPRAY	Necessary	62.88 FS	*59.74 FS
57	1		*2K-BODY ADHESIVE	Necessary	406.76 FS	*386.42 FS
58	1		*SEALANT CAN BE SPRAYED	Necessary	61.67 FS	*58.59 FS
59	1		*COVER FOR LOCK CARRIER TI END PANEL TRIM COVER	Deformed	210.62 FS	*200.09 FS
60	1		*THINKWARE 2CH CAMERA 32GB	Not Necessary	626.07 FS	*- FS
61	1		*FRT NUMBER PLATE	Bent	80.00 FS	*80.00 FS
62	1		*REAR NUMBER PLATE	Scratched	80.00 FS	*80.00 FS
63	1		*FRT MEMBER	Bent	197.35 FS	*197.35 FS
64	1		*SUPPORT FOR LOCK CARRIER	Bent	112.01 FS	*112.01 FS
65	1		*HEAT SHIELD FOR EXHAUST M	Bent	218.09 FS	*218.09 FS
66	1		*REAR PARKING SENSOR WIRE HARNESS	Cut	110.08 FS	*110.08 FS
67	1		*WARNING BUZZER SPEAKER	Not Working	54.95 FS	*54.95 FS
68	1		*CONTROL UNIT FOR PARK STE	Not Working	420.64 FS	*420.64 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 21,306.83 16,066.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	LABOUR FRT	New	2,520.00	840.00
4	SPRAY PAINT FRT	New	2,400.00	800.00
5	LABOUR REAR	New	4,800.00	3,360.00
6	SPRAY PAINT REAR	New	4,800.00	2,400.00
7	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
8	CLEAN UP GLASS CHIPS	New	840.00	420.00
9	R&R REAR W/SCREEN	New	840.00	840.00
10	R&R REAR LUGGAGE TRIM	New	840.00	420.00
11	REAR WATER LEAK TEST	New	150.00	150.00
12	REAR W/SCREEN SOLAR FILM	New	400.00	400.00
13	R&R REAR SEAT	New	840.00	420.00
Gross Labour Cost (\$)			20,030.00	11,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >