

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014613/UEA3Q2
Date: 04/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993928
Claimant Vehicle No :	SKT871S	Insured Vehicle No :	GBK747Y
Date of Loss:	23/12/2020	Nature of Claim:	TP
		Claim No:	7977713859SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT871S	Engine No:	2AZF201330
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Chassis No:	ACR507071318
Reg. Date:	02/10/2009 (Man. Year: 2008)	Odometer:	268579 km
Colour:	Silver		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/35ZR20	Rear Tyre Size:	245/35ZR20
Front Left Side:	Kinforest 6 mm	Rear Left Side:	Kinforest 6 mm
Front Right Side:	Kinforest 6 mm	Rear Right Side:	Kinforest 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,305.55	2,387.00	5,918.55	71.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	780.00	1,260.00	61.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,345.55	3,167.00	7,178.55	69.39
Approved Total (Overridden) (S\$)		2,500.00		

Nett Amount (S\$)	10,345.55	2,500.00	7,845.55	75.84
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
Nett Liability (S\$)		3,100.00		

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 30/12/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Profi Automotive
 1 Kaki Bukit Ave 6, Autobay@Kaki Bukit #02-48/50
 Singapore S417883

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	1,317.80 FL	*845.10 FL
2	1		*FRONT BUMPER RETAINER LH	Bent	131.30 FL	*85.00 FL
3	1		*FRONT BUMPER SPONGE	Not Necessary	130.30 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	381.80 FL	*- FL
5	1		*FRONT BUMPER GRILLE	Not Necessary	481.80 FL	*- FL
6	1		*FRONT BUMPER UNDER DUST COVER (TORN)	Not Consistent With The Impact	396.80 FL	*- FL
7	1		*FROTN FOG LAMP LH	Cracked	423.40 FL	*399.50 FL
8	1		*FROTN FOG LAMP BRACKET	Cracked	160.80 FL	*160.80 FL
9	1		*FRONT HEADLAMP LH	Cracked	1,397.50 FL	*1,397.50 FL
10	1		*FRONT FENDER LH	Repair	845.60 FL	*- FL
11	1		*FRONT FENDER INNER SHIELD LH	Torn	297.90 FL	*188.10 FL
12	1		*FRONT SHOCK ABSORBER LH	Not Necessary	601.60 FL	*- FL
13	1		*FRONT KNUCKLE ARM LH	Not Necessary	722.80 FL	*- FL
14	1		*FRONT LOWER ARM LH	Not Necessary	742.30 FL	*- FL
15	1		*FRONT WHEEL HUB AND BEARING LH	Not Necessary	594.30 FL	*- FL
16	1		*FRONT WING MIRROR ASSEMBLY LH	Not Necessary	901.40 FL	*- FL
17	1		*SET FRONT BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
18	1		*SET FRONT FENDER INNER TRIM CLIP	Necessary	40.00 FS	*40.00 FS
19	1		*RIM	Repair	600.00 FS	*- FS
20	1		*FRONT TYRE RH	Serviceable	400.00 FS	*- FS
21	1		*BT BRAKE FLUID	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,687.40	3,156.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,381.85	769.00
Total Parts (\$\$)	8,305.55	2,387.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK ALL WIRING AND LIGHTNING SYSTEM	New	120.00	20.00
2	COMPUTERISED AND CHECK ALL WHEEL ALIGNMENT	New	150.00	60.00
3	REMOVE AND REPLACE FRONT WHEEL UNDERCARRIAGE PARTS	New	250.00	0.00
4	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	New	800.00	300.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	600.00	400.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	0.00
Gross Labour Cost (S\$)			2,040.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >