

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20014614/UBA3Q2
Date: 30/03/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SJZ5391H	Insured Vehicle No :	SH6722T
Date of Loss:	27/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120507

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ5391H	Engine No:	CAV231493
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 TSI (A)	Chassis No:	WVWZZZ13ZBV014284
Reg. Date:	03/12/2010 (Man. Year: 2010)	Odometer:	176050 km
Colour:	Red		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,959.34	7,205.48	8,753.86	54.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	1,810.00	2,000.00	52.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,769.34	9,015.48	10,753.86	54.40
Approved Total (Overridden) (\$\$)		7,200.00		
Nett Amount (\$\$)	19,769.34	7,200.00	12,569.34	63.58
+ Car Rental (9.0 x S\$120.00/day) (\$\$)		1,080.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Doc Fees (\$\$)		60.00		
Nett Liability (\$\$)		8,347.45		
Global Sum Settlement (\$\$)		8,100.00		

INSPECTION

Date of Assignment:	28/12/2020		
Date Inspected:	29/12/2020 Inspected At:	Nineteen Autowerks Pte Ltd (Blk13) BLK 13 KAKI BUKIT ROAD 4 #01-05 BARTLEY BIZ CENTRE Singapore 417807	
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2021)
Parts:	144	VOLKSWAGEN SCIROCCO 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ5391H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Repair	1,895.00 FL	*- FL
2	1		*FRONT DOOR OUTER MOULDING LH	Cut	285.50 FL	*164.30 FL
3	1		*FRONT FENDER INNER SHIELD LH	Torn	225.40 FL	*192.20 FL
4	1		*FRONT WHEEL BEARING ,HUB ASSY LH	Bent	778.30 FL	*650.00 FL
5	1		*FRONT KNUCKLE ARM LH	Bent	855.40 FL	*588.20 FL
6	1		*FRONT LOWER ARM LH	Buckled	586.30 FL	*566.00 FL
7	1		*FRONT SHOCK ABSORBER LH	Serviceable	1,286.70 FL	*- FL
8	1		*HEADLAMP ASSY LH	Scratched	1,228.60 FL	*1,022.00 FL
9	1		*HEADLAMP LOWER BRACKET LH	Not Necessary	157.80 FL	*- FL
10	1		*FRONT BUMPER	Deformed / Torn	1,625.40 FL	*1,475.62 FL
11	2		*FRONT BUMPER BRACKET	Not Necessary	190.40 FL	*- FL
12	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	346.00 FL	*- FL
13	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	326.40 FL	*- FL
14	1		*FRONT DOOR VIEW MIRROR LH	Damaged	482.50 FL	*482.50 FL
15	1		*FRONT DOOR VIEW MIRROR GLASS LH	Broken	298.60 FL	*155.00 FL
16	1		*FRONT DOOR GLASS LH	Cracked	388.90 FL	*388.90 FL
17	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
18	1		*SET FRONT DOOR TRIMBOARD CLIPS LH	Not Necessary	60.00 FS	*- FS
19	1		*FRONT DOOR PROTECTOR LH	Not Necessary	180.00 FS	*- FS
20	1		*ROCKER PANEL GARNISH LH	Torn	520.00 FS	*520.00 FS
21	1		*FRONT FENDER LH (CUSTOMIZED)	Badly Dented	1,250.00 FS	*600.00 FS
22	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*40.00 FS
23	1		*FRONT ALLOY RIM LH	Cracked	1,450.00 FS	*600.00 FS
24	1		*FRONT TYRE LH	Serviceable	620.00 FS	*- FS
25	1		*FRONT SUSPENSION COIL COVER (ACCESSOIRES) LH	Serviceable	1,250.00 FS	*- FS
26	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,507.20	7,489.72
- List Item Discount on L Items 5.00/5.00% (\$\$)	547.86	284.24
Total Parts (\$\$)	15,959.34	7,205.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND STRAIGHTEN PARTS ON ACCIDENT AREA	New	1,500.00	580.00
2	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	80.00	20.00
3	R&R LH FRONT DOOR COMPONENT	New	100.00	0.00
4	R&R LH FRONT TYRE AND BALANCING	New	100.00	0.00
5	R&R LH FRONT UNDERCARRIAGE	New	480.00	120.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
7	TO APPLY UNDERCOATING FOR RUST PROOFING	New	200.00	30.00
8	SPRAY PAINTING ON ACCIDENT AREA	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			3,810.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >