

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG20014615/AGA3Q2

Date:

12/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900165175

Claimant Vehicle No : SLP2794C**Insured Vehicle No :**

SMP1046Z

Date of Loss: 24/12/2020

Nature of Claim:

TP

Claim No:

0272670515SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLP2794C**

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)

Engine No: CVN038676

Reg. Date: 30/05/2017 (Man. Year: 2017)

Chassis No: WAUZZZF43HA162588

Colour: Blue

Odometer: 68486 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,671.60	3,379.04	2,292.56	40.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,852.00	3,072.00	2,780.00	47.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,523.60	6,451.04	5,072.56	44.02
+ GST 7.00/7.00% (S\$)	806.65	451.57	355.08	44.02

Nett Amount (S\$)	12,330.25	6,902.61	5,427.64	44.02
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,204.61		

INSPECTION

Date of Assignment: 28/12/2020

Date Inspected: 30/12/2020

Estimated Period of Repair: 5.0 days

Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -RH	Dented	758.00 FS	*613.20 FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	200.00 FS	*- FS
3	1		*FRONT FENDER BRACE -RH FRONT	Not Necessary	117.00 FS	*- FS
4	1		*FRONT FENDER BRACKET -RH	Not Necessary	35.00 FS	*- FS
5	1		*FRONT FENDER CLOSING ELEMENT -RH	Not Necessary	49.00 FS	*- FS
6	1		*WHEEL HOUSING LINER -RH	Not Necessary	239.00 FS	*- FS
7	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
8	1		*STONE CHIP GUARD	Not Necessary	50.00 FS	*- FS
9	1		*TOP FENDER LEDGE COVER -UPPER	Not Necessary	31.00 FS	*- FS
10	1		*TOP FENDER LEDGE COVER -LOWER	Not Necessary	23.00 FS	*- FS
11	1		*FRONT DOOR -RH	Dented	2,553.60 FS	*2,553.60 FS
12	1		*FRONT DOOR OUTER SEAL -RH	Necessary	203.00 FS	*164.00 FS
13	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
14	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
15	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	870.00 FS	*- FS
16	1		*FRONT DOOR CATCH	Not Necessary	104.00 FS	*- FS
17	1		*TYRE PRESSURE DATE PLATE	Necessary	37.00 FS	*29.84 FS
18	1		*SUNDRIES	Necessary	200.00 FS	*18.40 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	5,671.60	3,379.04
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	280.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	280.00	280.00
3	TO DISMANTLE FRONT BUMPER ,RHS FRONT FENDER ,AND RHS FRONT DOOR .TO RENEW RHS FRONT FENDERAND RHS FRONT DOOR .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,800.00	1,500.00
4	TO RESPRAY THS FRONT FENDER AND RHS FRONT DOOR	New	2,300.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,852.00	3,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >