

Adjuster Letter/DV not verified.
This claim is to be authorized on the insurer's behalf.
Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.
Click on 'View Letter/DV' to verify the offer.

You cannot authorize this offer because
Adjuster Letter/DV not verified.
File to be authorized by your superior.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20014617ABA3Q2
Date: 14/05/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMP6201J	Insured Vehicle No :	SHD3541U
Date of Loss:	22/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120437

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP6201J	Engine No:	R16B25511153
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650KT001040
Reg. Date:	03/10/2019 (Man. Year: 2019)	Odometer:	8715 km
Colour:	Blue		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,018.00	518.58	499.42	49.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,410.00	2,070.00	59.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,498.00	1,928.58	2,569.42	57.12
Approved Total (Overridden) (S\$)		1,928.57		
(S\$)	4,498.00	1,928.57	2,569.43	57.12
+ GST 7.00/7.00% (S\$)	314.86	135.00	179.86	57.12
Nett Amount (S\$)	4,812.86	2,063.57	2,749.29	57.12
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
Nett Liability (S\$)		2,384.57		

INSPECTION

Date of Assignment:	29/12/2020		
Date Inspected:	04/01/2021	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2021)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP62011)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY ,RR.BUMPER	Deformed	462.90 FS	*462.90 FS
2	1		*SPACERR.RR BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
3	1		*SPACERL.RR BUMPER SIDE	Necessary	8.62 FS	*8.62 FS
4	1		*GARNISH ,R.RR BUMPER SIDE	Cut	6.37 FS	*6.37 FS
5	1		*CLIP BUMPER (7 PCS)	Necessary	12.07 FS	*12.07 FS
6	1		*COVERR FINISHER	Not Necessary	9.00 FS	*- FS
7	1		*BEAM COMPRR BUMPER	Not Necessary	135.00 FS	*- FS
8	1		*SENSOR ASSY ,PARKING	Not Necessary	111.30 FS	*- FS
9	1		*TAILLIGHT ASSYR	Not Necessary	214.12 FS	*- FS
10	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	1,018.00	518.58
---------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	150.00	100.00
2	REMOVE & INSTALL REVERSE SENSORS	New	180.00	140.00
3	RESET VEHICLE SMART ENTRY SYSTEM	New	450.00	0.00
4	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	New	1,500.00	650.00
5	SPRAY PAINTING ON REPAIRED AND REPLACED AREAS	New	1,200.00	520.00
Gross Labour Cost (S\$)			3,480.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >