

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20014622/DQD3Q2

Date: 10/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001339688

Claimant
Vehicle No : SMT3756Z

Insured Vehicle No : SLW9626Y

Date of Loss: 27/12/2020

Nature of Claim: TP

Claim No: 251345

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMT3756Z**

Make & Model: HONDA HR-V, 1.5 DX CVT (A)

Engine No: L15B5672557

Reg. Date: 02/06/2020 (Man. Year: 2020)

Chassis No: JHMRU1810JX202549

Colour: Blue

Odometer: 45521 km

Engine Capacity: 1496 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 5 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side:

Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,499.90	2,172.72	19,327.18	89.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,020.00	1,280.00	4,740.00	78.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,519.90	3,452.72	24,067.18	87.45
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	27,519.90	2,750.00	24,769.90	90.01
+ GST 7.00/7.00% (S\$)	1,926.39	192.50	1,733.89	90.01
Nett Amount (S\$)	29,446.29	2,942.50	26,503.79	90.01

INSPECTION

Date of Assignment: 29/12/2020

Date Inspected: 29/12/2020 Inspected At:

JWG International Pte Ltd (HQ)

Blk 10, Ang Mo Kio Ind Park 2A,, #03-

08 AMK AutoPoint

Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Mar 2021)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT3756Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,380.00 FL	*877.90 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	385.00 FL	*175.60 FL
3	1		*TAILGATE NO PLATE TOP GARNISH	Not Necessary	412.00 FL	*- FL
4	1		*SET TAILGATE NO PLATE TOP CHROME GARNISH	Not Necessary	304.00 FL	*- FL
5	2		*TAILGATE LAMP L+R	Not Necessary	1,379.20 FL	*- FL
6	1		*TAILGATE SWITCH	Not Necessary	385.50 FL	*- FL
7	1		*TAILGATE LOCK	Not Necessary	417.10 FL	*- FL
8	1		*TAILGATE HONDA LOGO	Necessary	81.40 FL	*81.40 FL
9	1		*TAILGATE HRV EMBLEM	Necessary	73.00 FL	*73.00 FL
10	1		*TAILGATE I-VTEC EMBLEM	Necessary	93.00 FL	*93.00 FL
11	1		*TAILGATE INNER TRIM BOARD LOWER	Not Necessary	513.92 FL	*- FL
12	1		*TAILGATE WEATHER STRIP	Not Necessary	343.20 FL	*- FL
13	2		*TAILGATE DAMPER LH/RH	Not Necessary	711.96 FL	*- FL
14	2		*TAILGATE HINGE LH/RH	Not Necessary	220.00 FL	*- FL
15	1		*SET TAILGATE STOPPERS	Not Necessary	120.00 FL	*- FL
16	2		*TAIL LAMP L+R	Not Necessary	1,549.20 FL	*- FL
17	2		*TAIL LAMP PANEL L+R	Not Necessary	590.00 FL	*- FL
18	1		*TAIL LAMP LOWER GARNISH L+R	N/s Cut/O/s Not Necessary	790.20 FL	*241.60 FL
19	1		*REAR BUMPER	Distorted/Mounting Broken	998.00 FL	*508.70 FL
20	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	115.00 FL	*- FL
21	1		*REAR BUMPER UNDER COVER	Mounting Broken	318.40 FL	*158.40 FL
22	4		*REAR BUMPER SENSOR HOLDER	Not Necessary	80.00 FL	*- FL
23	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	1,402.00 FL	*- FL
24	1		*REAR BUMPER REFLECTOR L	Mounting Broken	194.58 FL	*156.30 FL
25	1		*REAR BUMPER REFLECTOR R	Not Necessary	194.58 FL	*- FL
26	1		*REAR END PANEL	Repair	882.49 FL	*- FL
27	1		*REAR END PANEL TOP GARNISH	Not Necessary	342.84 FL	*- FL
28	2		*REAR FENDER L+R	Not Necessary	2,505.60 FL	*- FL
29	2		*REAR FENDER FLARE L+R	Not Necessary	627.60 FL	*- FL
30	2		*REAR FENDER INNER TRIM BOARD L+R	Not Necessary	735.40 FL	*- FL
31	1		*REAR KEYLESS ENTRY SENSOR	Not Necessary	338.40 FL	*- FL
32	1		*REAR KEYLESS ENTRY BUZZER	Not Necessary	329.41 FL	*- FL
33	1		*SPARE WHEEL PANEL	Not Necessary	1,120.40 FL	*- FL
34	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	512.90 FL	*- FL
35	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	385.00 FL	*- FL
36	2		*SPARE WHEEL SIDE PANEL LH/RH	Not Necessary	789.42 FL	*- FL
37	2		*SPARE WHEEL QUARTER PANEL LH/RH	Not Necessary	625.66 FL	*- FL
38	1		*REAR EXHAUST PIPE	Not Necessary	1,104.46 FL	*- FL
39	1		*SET REAR EXHAUST MOUNTING	Not Necessary	110.00 FL	*- FL
40	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	209.55 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	4		*REAR BUMPER SENSOR	Damaged	953.60 FS	*220.00 FS
42	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
43	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
44	1		*TAILGATE NO PLATE TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*TAILGATE NO PLATE TOP CHROME GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
46	1		*TAILGATE LAMP CLIPS	Not Necessary	50.00 FS	*- FS
47	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
50	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
51	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
52	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
53	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
54	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
55	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
56	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
57	1		*SPARE WHEEL QUARTER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
58	1		*SPARE WHEEL SIDE PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 26,233.97 2,645.90
- List Item Discount on L Items 20.00/20.00% (\$\$) 4,734.07 473.18

Total Parts (\$\$) 21,499.90 2,172.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIAE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	500.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	450.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	30.00
5	TO RNR REVERSE CAMERA	New	100.00	0.00
6	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	250.00	120.00
7	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
9	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS.RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
11	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	40.00
Gross Labour Cost (\$\$)			6,020.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >